

29-02285

POD

Field Exam 10/24/01




Irrigation well inside well house (csaxton 10/24/01).

29-02285

Label

Field Exam 10/24/01



Irrigation pump label. Make us U.S. Electrical Motors: HP - 30: SN - 1059472: Cycles -60 (csaxton 10/11/01).

29-02285

POD

Field Exam 10/24/01



One of two domestic wells. This one is located next to the road at the south of the property between the home of the claimant and his son (csaxton 10/24/01).

29-02285

POD

Field Exam 10/24/01



Out take pipes exiting the irrigation well. Irrigation well behind me in picture. Second of two domestic wells just to the left of the picture. Picture taken looking East (csaxton 10/24/01)