

29-02342A

POU

Field Exam: 8/13/02



Looking South. A portion of the claimed POU was resumed during the irrigation season of 2002. Picture shows the irrigated POU. Boundary between sagebrush and pasture ground shows the line between irrigated/cultivated ground and what is not irrigated (csaxton).