

29-4101A

- Need evidence of priority - letters indicate 1942
- Pond shape as noted on 1987/88 Rapp photography.
- Is lower part irrigated by Walker Ck or Marsh Ck?

- Source : Walker Creek.

Ditches go North & South in the upper portion of the field and not the lower section. Verify use.

4/29/02

- Hammond - previous owner before Henrichs.
- George + Marine Henrichs grandparents.
- Keith + Jo Henrichs parent.
- Curtis + Dedeana Dunn 1992 - purchased.

33 acres.

E. Side Irrigation Co.

Stock year round.
30-40 head.

2-4 nurse cows

Irrigation depends on snow. They start as soon as the snow melts.

Dunn

- Walker Ck diversion

12:56pm (11:56am)

file name DUNNWC.

N42° 43.429' W112° 14.186'

- photo looking N @ POD.

8S 36E Sec. 15 NESW.