


29-04442

POD

Field Exam 8/22/01



Looking North East. Claimant aquired the property November 2000. He said that when he purchased the property through HUD there was structures in the creek where a pump would have been set up. Picture shows power pole that ran power to pump. East FK of Mink Creek Road is in background behind the trees (csaxton 8/30/01).

29-04442

POU

Field Exam 8/22/01



Looking South. Napp indicates that this field could have been irrigated in 1987. Statement from neighbor Mrs. Norwood, said the land had been historically irrigated by original claimant James Marshall. Marshall sold the property in 1997. Even if no irrigation took place after Mr. Marshall sold the property, that is only 4 years of non-use. Recommend irrigation as seen on Napp photography (csaxton 8/30/01).

29-04442

POU

Field Exam 8/22/01



Looking South. Napp indicates that this field could have been irrigated in 1987. Statement from neighbor Mrs. Norwood, said the land had been historically irrigated by original claimant James Marshall. Marshall sold the property in 1997. Even if no irrigation took place after Mr. Marshall sold the property, that is only 4 years of non-use. Recommend irrigation as seen on Napp photography (csaxton 8/30/01).