

24-2005A

JR SIMPLOT



IMG_1499

Photo number

Photo Rename

11/10/2006

Date

5:05

Time

AM

PM

Looking North easterly at phase I
settling pond. The slurry is pumped
to the phase II pond to settle out. Then
it gets pumped to the phase I pond
to settle out again. Then the water
is pumped back to the plant to be
reused again. Then it's pumped back
again from the plant to the phase II
pond. Closed loop system, no water
leaves the system. CS

24-2005A

JR SIMPLOT



IMG_1497

Photo number

Photo Rename

11/10/2006

Date

5:04

Time

AM

PM

Verlin Andrews shut the headgate from
Roberts Creek to the ditch to phase II
pond.
this ditch is on south side of phase I.

24-2005A

JR SIMPLOT



IMG_1498

Photo number

Photo Rename

11/10/2006

Date

5:05

Time

AM

PM

Verlin is attempting to pull out the
canvas dam from Roberts creek.
but it is already frozen to the soil.