

WELL-DRILLER'S REPORT

REC-
JUL 20 1999

076683

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat: _____ : _____ Long: _____ : _____

Well Number:
898

sketch map location must agree with written location

		X	

City **HAYDEN**

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ **Blk.** _____ **Sub. Name** _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
BENTONITE	0	30	9 BAGS	OVERBORE

Was drive shoe seal tested? ☐ Y ☐ N How?

Diameter	From	To	Gauge	Material
8	+2	30	.250	STEEL
4	-5	165	.160	PVC

Length of Headpipe _____ **Length of Tailpipe** _____

Screens	Screen Type
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

From	To	Alt Elev	Number	Diameter	Material	Casing	Line
125	165	1/8X4	170	4	PVC	☐	☒

Depth flow encountered _____ ft. Describe access port or control devices:

Yield gal./min.	Drawdown	Pumping Level	Time
40+		165	1 HR

Depth first Water encountered 160

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

[illegible]

and Supervisor or Operator L. S. [Signature] Date 7/2/99

(Sign Once if Firm Official and Operator)

(Louie Hanner)