

IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

Office Use Only			
Inspected by _____			
Twp _____	Rge _____	Sec _____	
1/4 _____	1/4 _____	1/4 _____	
Lat: _____	Long: _____		

1. WELL TAG NO.

DRILLING PERMIT N 40250 833406

Other IDWR No _____

2. OWNER:

Name Ben & Linda Bomar

Address 10968 N Government Way / Box 102

City Hayden

State ID

Zip 83835

3. LOCATION OF WELL by legal description:

N		Twp 53N North ☒ or South ☐	
Rge 03W East ☐ or West ☒			
Sec 07 1/4 SW 1/4 NE 1/4			
Gov't Lot _____ County Kootenai			
Lat _____ Long _____			

Address of Well Site: (see next line)

31285 Clagstone Road

City Athol

Lot _____ Blk _____

Sub. Name (see next line)

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK			Amount	Method
Material	From	To	Sacks/Lbs	
Bentonite	0	18	6 Sacks	Pour In
Granular				

Drive Shoe Used? ☒ Y ☐ N Shoe Depth(s) _____ Ring Bit 523

Drive Shoe Seal Tested? ☐ Y ☒ N How? _____

8. CASING/LINER

Diam	From	To	Gauge	Material	Casing	Liner	Weld	Thrded
6	2	522	0.250	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length Headpipe _____ Length Tailpipe _____

9. PERFORATIONS/SCREENS

☒ Perforations? Method Air Perforator
☐ Screens? Screen Type _____

From	To	Slot	Nmbr	Diam	Material	Casing	Liner
500	520	1X1/4	200	6	Steel	☒	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL or ARTESIAN PRESSURE

470 ft. below ground. Artesian pressure _____ lb.

Depth flow encountered _____ 470 ft. Describe access port or

control devices: Steel Cap Welded

53N 3W 7

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pump Level	Time
20	100%	520	1Hr

Water Temp. _____ Cold Bottom hole temp. _____ Cold

Water Quality test or comments: (below) Depth first Water Encountered 470

Cold, Some Color, No Smell

12. LITHOLOGIC LOG (Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality and Temperature	Water	
				Y	N
8	0	1	Top Soil	☐	☒
8	1	300	Sand & Gravel 3/4 minus	☐	☒
8	300	310	Bolder	☐	☒
8	310	360	Sand & Gravel 3/4 minus	☐	☒
8	360	450	Sand & Gravel 1/4 minus	☐	☒
8	450	460	Clay Gray with Gravel	☐	☒
8	460	470	Sand & Gravel 1/2 minus	☐	☒
8	470	523	Sand & Gravel 1 inch minus	☒	☐

RECEIVED
JUN 30 2005
IDWR/NID

Completed Depth 522 (Measurable)
Date: Started 5/23/05 Completed 5/25/05

13. DRILLERS CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name United Drilling Inc. Firm No 414

Firm Official and *Jason C. Beckham* Date 6/2/05

Supervisor or Operator Jason C. Beckham Date 6/2/05