

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Inspected by _____			
Twp _____	Rge _____	Sec _____	
_____ 1/4	_____ 1/4	_____ 1/4	
Lat: : : _____	Long: : : _____		

1. WELL TAG NO. **D0013520**

DRILLING PERMIT NO _____

Other IDWR No. _____

2. OWNER:

Name **Jeffrey & Virginia Meads**Address **7887 E Sunshine Way**City **Athol** State **ID** Zip **83801**

3. LOCATION OF WELL by legal description:

N		Twp	53N	North	☒ or	South	☐
W		Rge	03W	East	☐ or	West	☒
S		Sec	27	1/4 NW 1/4 NE 1/4			
				10 Ac 40 Ac 160 Ac			
		Gov't Lot		County Kootenai			
		Lat		Long			

Address of Well Site: (see next line)

Highway 95 to Sunshine Way _____

Lot _____ Blk _____ Sub. Name (see next line) _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			Amount	Method
Material	From	To	Sacks/Lbs	
Bentonite	0	18	6 sacks	pour in

Drive Shoe Used? ☒ Y ☐ N Shoe Depth(s) _____ 358Drive Shoe Seal Tested? ☐ Y ☒ N How? _____

8. CASING/LINER

Diam	From	To	Gauge	Material	Casng	Liner	Weld	Thrded
6	2	358	0.250	steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length Headpipe _____ Length Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations? Method _____
☐ Screens? Screen Type _____

From	To	Slot	Nmbr	Diam	Material	Casng	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL or ARTESIAN PRESSURE

400 ft. below ground. Artesian pressure _____ lb.
Depth flow encountered _____ 489 ft. Describe access port or
control devices: **Steel cap welded**

11. WELL TESTS

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pump Level	Time
1	100%	799	1 hr.

Water Temp. _____ cold Bottom hole temp. _____ cold

Water Quality test or comments: (below) _____ Depth first Water Encountered _____ 489
clear, no smell

12. LITHOLOGIC LOG (Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality and Temperature	Water	
				Y	N
8	0	18	Topsoil & sand & gravel	☐	☒
8	18	180	Sand & gravel - 1" minus	☐	☒
8	180	185	Boulder	☐	☒
8	185	227	Sand & gravel - 3/4" minus	☐	☒
8	227	280	Sand & gravel - 3/4" minus	☐	☒
8	280	287	Boulder	☐	☒
8	287	314	Sand & gravel & cobbles	☐	☒
8	314	333	Sand & gravel with decomposed granite	☐	☒
8	333	358	Granite - green/white/black	☐	☒
6	358	489	Granite - green/white/black - medium	☒	☐
			1 gpm @ 489	☐	☐
6	489	520	Granite - black & white - hard	☐	☒
6	520	580	Granite - green/white/black - hard	☐	☒
6	580	585	Granite - purple/black/white - hard	☐	☒
6	585	687	Granite - black/white/green	☐	☒
6	687	800	Granite - black/white/green - hard	☐	☒

Completed Depth _____ 800 _____ (Measurable)
Date: Started _____ 8/1/00 _____ Completed _____ 8/10/00

13. DRILLERS CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name **United Drilling Inc.** Firm No **414**Firm Official *Jason C. Beckham* Date **8/11/00**Supervisor or Operator **Jason C. Beckham** Date **8/11/00**

FORWARD WHITE COPY TO WATER RESOURCES