

Date: August 26, 2009

To: Monica Van Bussum

From: Bob Foster

Re: 75-4501, Robert St. Clair

I made an on site visit to the Robert St. Clair property on August 25, 2009. The purpose of this visit was to verify irrigation use on the property. I was accompanied by John Cranney, a local outfitter who leases the St. Clair property for a hunting camp.

An inspection of the property revealed no evidence of irrigation. Most of the irrigable property is cover in sagebrush ranging 2-4 feet in height. There was no evidence of any active point of diversion for irrigation purposes. There was evidence of some very old ditches on the property, but these ditches were barely discernable and would require extensive reconstruction.

The only water use I observed was use from a spring source for the outfitter camp.

75-4501




Photo taken looking east from outfitter camp. Lower POU and cabin in photo 8/25/09

75-4501



Photo looking east from outfitter camp. Lower POU and cabin in photo 8/25/09



75-4501 1987 photography