

11/16

Water Right 2-39

Original priority date claimed 04/01/1952

Figure 1 is a picture of the land lying just below CJ Strike Dam that comprises the Place of Use for 2-39. The Dam was completed in 1952. The lower portion of the picture shows bare land that appears to have been recent shaped and graded. A large gravel truck is also seen traveling in lower portion of the photo. Also apparent is there are no large trees in the house developing in the upper portion of the photo. This dates the photo to sometime soon after dam completion in either 1952 or 1953. The area of interest below the dam appears to have been graded and ditched for contour irrigation. There also appears to be a few trees planted on those areas bordering the river below the dam. The area does not appear to be have been planted yet or just recently planted. This provides ample evidence of irrigation taking place sometime soon after dam completion.




Figure 1: Showing the area below CJ Strike Dam prepared for irrigation soon after dam completion in 1952.

SCANNED
NOV 16 2009