

RECEIVED

Form 238-7
1/84

SEP 21 1995

NORTHERN REGION
IDWR

IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

Use Typewriter
or
Ball Point Pen

1. DRILLING PERMIT NO. 95-95-41-161-000
Other IDWR No. _____

2. OWNER:

Name Ruth Ockert / Lynne Getchell
Address 121 Francis dr.
City El Cajon State CA Zip 92019

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

	Twp. <u>S2</u>	North ☒ or South ☐
	Rge. <u>5</u>	East ☐ or West ☒
	Sec. <u>31</u>	1/4 <u>32</u> <u>31</u> <u>32</u> <u>31</u> <u>32</u> <u>31</u> <u>32</u>
	Gov't Lot _____	County <u>Kootenai</u>

Address of Well Site 11825 N. Three Forks Rd.
(Give at least name of road + Distance to Road or Landmark) City Post Falls

Lt. _____ Bk. _____ Sub. Name _____

4. PROPOSED USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK

☒ New Well ☐ Modify or Repair ☐ Replacement ☐ Abandonment

6. DRILL METHOD

☐ Mud Rotary ☒ Air Rotary ☐ Cable ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT Bags or Pounds	METHOD
Material	From	To		
<u>Bentonite</u>	<u>0</u>	<u>18.5</u>	<u>4</u>	<u>over bore</u>

Was drive shoe used? Y ☒ N ☐

Was drive shoe seal tested? Y ☒ N ☐ How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6</u>	<u>1.5</u>	<u>18.5</u>	<u>250</u>	<u>Steel</u>	☒	☐	☒	☐
<u>4</u>	<u>12</u>	<u>402</u>	<u>15</u>	<u>PVC</u>	☐	☒	☒	☐

Length of Headpipe 1.5 Length of Tailpipe 18.5

9. PERFORATIONS/SCREENS

☒ Perforations Method Saw cut
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
<u>362</u>	<u>402</u>	<u>1/8x5</u>	<u>36</u>	<u>4</u>	<u>PVC</u>	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

4 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: Welded plate
NE 1/4 31 52N 5W

FORWARD WHITE COPY TO WATER RESOURCES

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
<u>11</u>			<u>1 hr.</u>

Water Temp. cool Bottom hole temp. cold

Water Quality test or comments: good, no odor

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>8</u>	<u>0</u>	<u>3</u>	<u>Top Soil</u>		
<u>3</u>	<u>13</u>	<u>13</u>	<u>decomposed Granite</u>		
<u>13</u>	<u>13.5</u>	<u>13.5</u>	<u>granite</u>		
<u>6</u>	<u>18.5</u>	<u>402</u>	<u>granite</u>		
			<u>1st water 28' 1/2 gpm</u>		
			<u>2nd 116 1 gpm</u>		
			<u>3rd 260 1 5 gpm</u>		
			<u>4th 373 8.5 gpm</u>		

MICROFILMED

JAN 08 1998

Completed Depth 402 (Measurable)
Date: Started 9-8-95 Completed 9-12-95

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name AQUA DRILLING & EXPLORATION INC. Firm No. 163

Firm Official Scott M. Braun Date 9-12-95

and Supervisor or Operator Wendy Montoya Date 9-12-95

(Sign once if Firm Official & Operator)