

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
_____ 1/4 _____ 1/4 _____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D0044840

DRILLING PERMIT NO. 840067

Other IDWR No.

2. OWNER:


2. OWNER.
Name Bill Wagstaff

Address PO Box 868

City Liberty Lake State WA Zip 99019

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.



Twp. 49 North ☒ or South ☐
 Rge. 04 East ☐ or West ☒
 Sec. 9 1/4 SW 1/4 SE 1/4
 Gov't Lot _____ County Kootenai 10 acres 40 acres 160 acres
 Lat. : : Long. : :
 Address of Well Site Tall Pines Rd
City Coeur d'Alene
 (Give at least name of road + Distance to Road or Landmark)
 Lt. _____ Blk. E Sub. _____ Name Lyondale

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
Granular	0	18	8 sacks	Overbore
Bentonite				Dry Pack

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 19ft

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	19	250	steel	☒	☐	☒	☐
4"	13	260	200	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe_____ Length of Tailpipe_____

9. PERFORATIONS/SCREENS

Perforations Method 3/8" Spade Bit & Drill

Screens	Screen Type
---------	-------------

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
60	80	3/8"		4"	PVC	☐	☒
200	260	3/8"		4"	PVC	☐	☒
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

41 ft. below ground Artesian pressure lb.

Depth flow encountered 68 ft. Describe access port or control devices: 1" access port w/ cap

49N 4W 9

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
1-1/2		250	1 hour

Water Temp. cold Bottom hole temp. cold

Water Quality test or comments:

Depth first Water Encounter 68

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	1	Gravel		X
10	1	7	Clay w/ Sand		X
10	7	68	Granite, Hard		X
6	68	72	Granite, Fractured - Water 1-1/2gpm	X	
6	72	197	Granite, Medium w/ Fractures		X
6	197	260	Granite, Hard w/ Fractures		X
			Recommended pump depth is 250 feet.		
			RECEIVED JUN 21 2006 IDWR/North		
			RECEIVED AUG 01 2006 IDWR/North		
			RECEIVED NOV 02 2006 IDWR/North		
1					

Completed Depth 260 feet (Measurable)
 Date: Started 5/30/06 Completed 6/1/06

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name J & J Drilling, Inc. Firm No. 319

Firm Official [Signature] Date 6-20-66

Driller or Operator Don Anderson Date 6/19/06

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES