Form 238-7
6/02

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Well ID No.
Inspected by
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 053912
DRILLING PERMIT NO.
Water Right or Injection Well No.

2. OWNER:
Name Jerry & Georgia Willis
Address 1098 N. Morning Dr.
City Post Falls State Id. Zip 83854

3. LOCATION OF WELL by legal description:
You must provide address or Lot, Blk, Sub. or Directions to well.
Twp. 48 North ☑ or South ☐
Rge. 01 East ☐ or West ☑
Sec. 23, ____ 1/4 (10 acres) SW 1/4 (40 acres) NW 1/4 (160 acres)
Gov't Lot ____ County Kootenai
Lat: : : **Long:** : :
Address of Well Site 26275 So. Latour Cr.
(Give at least name of road + Distance to Road or Landmark) City Cataldo
Lt. ____ Blk. ____ Sub. Name

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☑ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply (Replacement etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD:
☐ Air Rotary ☑ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
Bentonite	0	19	4 Sacs	overbore

Was drive shoe used? ☑ Y ☐ N Shoe Depth(s) 26'
Was drive shoe seal tested? ☑ Y ☐ N How? water

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	-26	250	Steel	☑	☐	☑	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____
Packer ☐ Y ☑ N Type

9. PERFORATIONS/SCREENS PACKER TYPE
Perforation Method N/A
Screen Type & Method of Installation N/A

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. FILTER PACK N/A

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
8 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices:
6" Bolted well Cap

12. WELL TESTS:
☐ Pump ☑ Bailer ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
25+			

Water Temp. Cool Bottom hole temp. Cool
Water Quality test or comments: Good
Depth first Water Encounter 21'

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	19			
6	19	29			
	0	26	Boulders Cobbles Gravel and Sand & Broken Shale	X	
	26	29	Brown & Blue Shale	X	

Completed Depth 29' (Measurable)
Date: Started 8-7-07 Completed 8-21-07

14. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Valley Drilling Firm No. 683
Principal Driller Wayne Miller Date 8-15-07
and
Driller or Operator II ____ Date ____
Operator I ____ Date ____
Principal Driller and Rig Operator *Required.*