

OUTBUILDINGS


Owner John Miller
Address _____
City & State _____

Location 34-49-1W
47-P23

County _____

Sheet _____ of _____

Type of Building <u>Garage</u>	Year Constr. <u>1949</u>	Age _____	Area <u>240</u>	Per. <u>64</u>
Foundation <u>sub.</u>	Gr.	Units	Cost	Total
Exterior Walls <u>2x4-24" c. sheet</u>		<u>64</u>	<u>90</u>	<u>58</u>
		<u>512</u>	<u>1928</u>	<u>241</u>
Wall Height <u>8</u> ft. & Walls open or abutting _____ ft.				
1st Floor <u>2x6-24" c. sub. 7 ft.</u>		<u>240</u>	<u>2525</u>	<u>120</u>
2nd Floor _____				
Floor Finish _____				
Int. Wall Constr. % _____				
Ceiling _____				
Electrical <u>0</u>				
Plumbing <u>0</u>				
Heating <u>0</u>				
Windows <u>0</u>				
Doors <u>sub. hinge</u>				
Roof <u>2x4-24" c. sheet. R.R. 1/4 P</u>		<u>269</u>	<u>1926.09</u>	<u>145</u>
	Base Rate			
	Appraised <u>1-18-72</u> By <u>A</u> Structure Grade A B C <u>(D)</u>	Reproduction Cost	<u>564</u>	
	Computed _____ By _____ Area Adjustment Factor _____		<u>60 %</u>	<u>338</u>
	Reviewed _____ By _____ Depreciation Factor _____		<u>59 %</u>	<u>200</u>
	Constr. Cost _____ Market Value on _____		<u>19</u>	



Type of Building _____	Year Constr. _____	Age _____	Area _____	Per. _____
Foundation _____	Gr.	Units	Cost	Total
Exterior Walls _____				
Wall Height _____ ft. & Walls open or abutting _____ ft.				
1st Floor _____				
2nd Floor _____				
Floor Finish _____				
Int. Wall Constr. % _____				
Ceiling _____				
Electrical _____				
Plumbing _____				
Heating _____				
Windows _____				
Doors _____				
Roof _____				
	Base Rate			
	Appraised _____ By _____ Structure Grade A B C D _____	Reproduction Cost		
	Computed _____ By _____ Area Adjustment Factor _____		<u>%</u>	
	Reviewed _____ By _____ Depreciation Factor _____		<u>%</u>	
	Constr. Cost _____ Market Value on _____		<u>19</u>	

REMARKS:- _____