

IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

Office Use Only		
Inspected by _____		
Twp _____	Rge _____	Sec _____
1/4	1/4	1/4
Lat: : : _____	Long: : : _____	

1. WELL TAG NO. D0028421

DRILLING PERMIT N 803849

Other IDWR No _____

2. OWNER:

Name Charles & Dana Piozet

Address 668 S Essex #3

City Post Falls

State ID

Zip 83854

3. LOCATION OF WELL by legal description:

N		Twp <u>50N</u>	North ☒ or South ☐
Rge <u>06W</u>		East ☐ or West ☒	
Sec <u>13</u>		1/4 SW 1/4 NW 1/4	
Gov't Lot _____		County <u>Kootenai</u>	
Lat _____		Long _____	

Holland Road

City Post Falls

Lot _____ BIK _____ Sub. Name (see next line) _____

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			Amount	Method
Material	From	To	Sacks/Lbs	
Bentonite Gran.	0	18	5 Sacks	Pour-in

Drive Shoe Used? ☐ Y ☒ N Shoe Depth(s) _____

Drive Shoe Seal Tested? ☐ Y ☒ N How? _____

8. CASING/LINER

Diam	From	To	Gauge	Material	Casng	Liner	Weld	Thrded
6	+2	183	0.250	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length Headpipe _____

Length Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations? Method _____

☐ Screens? Screen Type _____

From	To	Slot	Nmbr	Diam	Material	Casng	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL or ARTESIAN PRESSURE

103 ft. below ground. Artesian pressure _____ lb.

Depth flow encountered 103 ft. Describe access port or

control devices: Steel Cap Welded

11. WELL TESTS:

☐ Pump

☐ Bailer

☒ Air

☐ Flowing Artesian

Yield gal./min.	Drawdown	Pump Level	Time
25	100%	218	1 Hour

Water Temp. _____

Cold

Bottom hole temp. _____

Cold

Water Quality test or comments: (below) Depth first Water Encountered 103

Clear, Cold, No Smell

12. LITHOLOGIC LOG (Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality and Temperature	Water	
				Y	N
8	0	3	Topsoil	☐	☒
8	3	103	Sand/Gravel - Fine with some clay seams	☐	☒
8	103	162	Sand/Gravel - Fine	☒	☐
8	162	175	Decomposed Granite - Brown/White	☐	☒
8	175	183	Granite - Purple/Black/White - Medium	☐	☒
6	183	187	Granite - Purple/Black/White - Medium	☐	☒
6	187	210	Granite - Brown/White - Soft	☒	☐
6	210	220	Granite - Purple/Black/White - Medium	☐	☒

Completed Depth 220 (Measurable)

Date: Started 6/20/03 Completed 6/20/03

13. DRILLERS CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm United Drilling Inc.

Firm No 414

Name

Firm Official

and

Supervisor or Operator Jason C. Beckham

Date 6/20/03

Date 6/20/03

50 N 6 W 13

Identify

Identify from: Taxlots

Taxlots

PIOZET DANA SUE ETVIR

Location: 2,272,117.589 1,835,594.656 Meters

Field	Value
OBJECTID	3676182
UPDATED	2/6/2009
PIN	50N06W-13-4700
OWNER	PIOZET DANA SUE ETVIR
ADDRESS1	18637 W HOLLAND RD
ADDRESS2	
CITY	POST FALLS
STATE	ID
ZIPCODE	83854
P_ADDRESS	18637 W HOLLAND RD
P_ZIPCODE	83854
SUB_NAME	
LEGAL1	TAX# 19530 [IN SE-NW] 13 50...
LEGAL2	
LEGAL3	
LEGAL4	
LEGAL5	
LEGAL6	<null>
ACRES	10
COUNTY	Kootenai
YEAR_BUILT	2003
SHAPE	Polygon
ParcelCount	1
SHAPE.area	40557.703125
SHAPE.len	825.754602

Identified 1 feature

start

Inbox - Microsoft ...

IDWR Work-flow S...

goody3.mxd - Arc...

10:40 AM