RECEIVED
Form 238-7
3/95
OCT 0 8 1996
NORTHERN REGION
IDWR

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

POSTED

Use Typewriter or Ballpoint Pen

0971C2

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 95 - 96 - N - 132 - 000
Other IDWR No. _____

2. OWNER:
Name DANA DUBE
Address 5145 E MULLIN
City POST FALLS State ID Zip 83854

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 52 North ☒ or South ☐
Rge. 3W East ☐ or West ☒
Sec. 32 , ____ 1/4 (10 acres) N/E 1/4 (40 acres) S/E 1/4 (160 acres)
Gov't Lot ____ County Kootenai
Lat: : : Long: : :
Address of Well Site DODD RD.
_____ City _____
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	+20	11 sacks	pour in

Was drive shoe used? ☐ Y ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	-158	.025	steel	☒	☐	☒	☐
4"	-140	-240		PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☒ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
180'	240'		200	3/8"	PVC	☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
160 ft. below ground Artesian pressure ____ lb.
Depth flow encountered 44/188/2 ft. Describe access port or control devices: steel cap welded

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
60 GPM			2 hrs

Water Temp. cold Bottom hole temp. cold
Water Quality test or comments: clear,cold, no smell
_____ Depth first Water Encountered 55

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8"	0	4	Topsoil		X
8"	4	20	Shale cobbles - clay		X
8"	20	50	Clay - brown - hard		X
8"	50	60	Shale - gravel - clay	X	
8"	60	80	Clay - brown - hard		X
8"	80	135	Clay - brown - hard		X
8"	135	153	Clay - black - soft		X
8"	153	158	Basalt - black - hard		X
6"	158	185	Basalt - black - hard		X
6"	185	185	Basalt - broken - (water - 25 GPM)	X	
6"	185	230	Basalt - black - hard		X
6"	230	233	Basalt - black - broken (water - 35 GPM)	X	
6"	233	237	Basalt - black - hard		X
6"	237	240	Sandstone - soft		X

Completed Depth 240' (Measurable)
Date: Started 9/01/96 Completed 9/03/96

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name United Drilling Inc. Firm No. 414
Firm Official [signature] Date 9/04/96
and
Supervisor or Operator Jason C. Beckham Date 9/04/96
(Sign once if Firm Official & Operator)

NESE 32 52N 3W

YELLOW/WHITE COPY TO WATER RESOURCES