Form 238
3/95
Stebbles Consulting and Management Services

RECEIVED
DEC 27 1995
NORTHERN REGION

POSTED

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

COPY

Use Typewriter or Ballpoint Pen

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 96-95-N-235
Other IDWR No. _____

2. OWNER
Name RICHEY, ED & ANN
Address 13810 S PINE BLVD
City CHENEY State WA Zip 99044

3. LOCATION OF WELL by legal description
sketch map location must agree with written location



Twp. 54 ☒ North or ☐ South
Rge. 04 ☐ East or ☒ West
Sec. 07 SE 1/4 SE 1/4 SE 1/4
Gov't Lot _____ County BONNER
Lat: : : Long: : :
Address of Well Site 800 RICHEY RD
City _____
(Give at least name of road + Distance to Road or Landmark)
Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
BENTONITE	0	18	3 BAGS	OVERBORE - DR

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) 0
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
4	-5	180	.200	PSI PVC	☐	☒	☐	☐
60	+1.5	18.5	.259	STEEL	☒	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☒ Perforations Method SKILL SAW
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
140	180	1/8X4	150	4	PVC	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
100 ft. below ground Artesian pressure 0 lb.
Depth flow encountered 0 ft. Describe access port or control devices:

SESE 7 54N 4W

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
11			

Water Temp. _____ Bottom Hole Temp _____
Water Quality test or comments: _____
Depth first Water encountered _____

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Water Y	Water N
				☐	☐
8	0	3	SOIL W/COBBLES	☐	☒
8	3	15	GRANITE DECOMP BROW	☐	☒
8	15	18	GRANITE BLACK & COPP	☐	☒
6	18	58	BLACK & WHITE W/COPP	☐	☒
6	58	64	APPROX 10 GPM	☒	☐
6	58	64	GRANITE BLACK & WHIT	☐	☐
6	64	106	GRANITE BLACK & COPP	☐	☒
6	106	124	W/WATER APPROX 1 GPM	☒	☐
6	106	124	GRANITE WHITE & GREE	☐	☐
6	124	180	GRANITE BLACK & WHIT	☐	☒

OFFICE USE ONLY
Inspected by TDK
Twp 54N Rge 4W Sec 07
NW SW NE SE

MICROFILMED
MAR 09 1999

Completed Depth 180 (Measurable)
Date: Started 08-05-95 Completed 08-09-95

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H20 WellService, Inc. Firm No. 448
Firm Official John Wheeler Date 12-26-95
and
Supervisor or Operator John Wheeler Date 12-26-95
(Signature if Firm Offical and Operator)