RECEIVED
JUN 28 1999
IDWR/North

Form 238-7
3/95

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

076497

Office Use Only
Inspected by _____
Twp____ Rge____ Sec____
____1/4____1/4____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 93-99-N-3 -____
Other IDWR No. D0010106

2. OWNER:
Name Alan Little
Address PO Box 4 Rockford
City Rockford State WA Zip 99030

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

POSTED

N / W / E / S

Twp. 46N North ☒ or South ☐
Rge. 5W East ☐ or West ☒
Sec. 19 , ____ (10 acres) 1/4 NW (40 acres) 1/4 NE (160 acres) 1/4
Gov't Lot ____ County Benewah
Lat: : : Long: : :
Address of Well Site Meredith Rd.
____ City ____
(Give at least name of road + Distance to Road or Landmark)

Lt.____ Blk.____ Sub. Name____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	18	250lbs	pumping
Barroid				

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 20 feet
Was drive shoe seal tested? ☐ Y ☒ N How?____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1	19	.25	steel	☒	☐	☐	☐
4		140	Sch	200PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe____ Length of Tailpipe____

9. PERFORATIONS/SCREENS
☐ Perforations Method____
☐ Screens Screen Type____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
55 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: 1" hole on well cap

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min	Drawdown	Pumping Level	Time
8gpm			

Water Temp. cold Bottom hole temp. ____
Water Quality test or comments: ____
____ Depth first Water Encountered 97-99

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	2	Topsoil		X
8	2	9	Clay, Brown & Hard		X
8/6	9	97	Shale, Grey & Medium		X
6	97	99	Shale, Fractured - Water 2.5gpm	X	
6	99	117	Shale, Grey & Medium		X
6	117	119	Shale, Fractured - Water 5.5gpm	X	
6	119	130	Shale, Grey & Medium		X
6	130	150	Shale, Tan & Medium		X
			Note: Recommended pump depth is 120 feet.		

Completed Depth 150 (Measurable)
Date: Started 6/15/99 Completed 6/15/99

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name J & J Drilling, Inc. Firm No. 319
Firm Official [signature] Date 6/24/99
and
Supervisor or Operator Don Anderson Date 6/23/99
(Sign once if Firm Official & Operator)

46N 5W 19

FORWARD WHITE COPY TO WATER RESOURCES

SCANNED
JUN 20 2011