

IDAHO DEPARTMENT OF WATER RESOURCES

RECEIVED
WELL DRILLER'S REPORT

NOV 06 1998

77859

Office Use Only			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat	:	Long	:

1. WELL TAG NO. D6451

Drilling Permit No:

Other IDWR No.

IDWR/North

95-98-N-195

2. OWNER

Well Number:

Name MILLER, THOMAS

797

Address E 5050 LANCASTER


City HAYDEN

State ID

Zip 83835

3. LOCATION OF WELL by legal description

sketch map location must agree with written location



Twp. 48



North or



South

Rge. 04



East or



West

E Sec. 20

1/4 SE 1/4 SW 1/4

Gov't Lot

County KOOTENAI

Lat:

Long:

Address of Well Site WINDY BAY

City CDA

(Give at least name of road + Distance to Road or Landmark)

Lt. Blk. Sub. Name

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation

☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK

check all that apply (Replacement, etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
BENTONITE	0	18	10	GRANULAR

Was drive shoe used? ☐ Y ☐ N Shoe Depth(s)

Was drive shoe seal tested? ☐ Y ☐ N How?

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	100	.250	STEEL	☒	☐	☒	☐

Length of Headpipe Length of Tailpipe

9. PERFORATIONS/SCREENS

☐ Perforations Method

☐ Screens Screen Type

From	To	Slot Size	Number	Diameter	Material	Casing	Liner

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

15 ft. below ground Artesian pressure lb.

Depth flow encountered ft. Describe access port or control devices:

11. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
50+			1 HR

POSTED

Water Temp. Bottom Hole Temp

Water Quality test or comments:

Depth first Water encountered 95

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

				Water	
Bore Dia	From	To	Remarks: Lithology, Water Quality, Temperature	Y	N
10	0	4	FILL	☐	☒
10	4	18	Basalt Broken W/Clay	☐	☒
8	18	59	Basalt Broken W/Clay	☐	☒
8	59	67	Clay	☐	☒
8	67	89	Basalt Broken W/Clay	☐	☒
8	89	100	Basalt Broken	☒	☐
5.5	100	107	Basalt Broken	☒	☐
RECEIVED NOV 06 1998 IDWR/North					
Completed Depth 107' (Measurable)					
Date: Started 10/21/98 Completed 10/22/98					

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O Well Service, Inc. Firm No. 448

Firm Official Date 10/22/98

and Supervisor or Operator Date 10/22/98

(Sign Once if Firm Official and Operator)

(Todd Morgan)

48N 4W 20

48N04W20NWSW

LOT 2

48N04W20NWSW

LOT 2

well

