

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Office Use Only		
Inspected by		
Twp	Rge	Sec
1/4	1/4	1/4
Lat	:	Long
:	:	:

1. WELL TAG NO. D0051942Drilling Permit No. 847397

Other IDWR No. _____

2. OWNER

Name BEELER, LARRY

Well Number:

1321Address BOX 751City PINEHURST State ID Zip 83850

3. LOCATION OF WELL by legal description

sketch map location must agree with written location

N			
W			
S			

Twp. 49N ☒ North or ☐ SouthRge. 01W ☐ East or ☒ WestSec. 34 1/4 NW 1/4 SW 1/4Gov't Lot _____ County KOOTENAILatitude: N47:31:768 Longitude: W118:41:978Address of Well Site MEADOW RD.City CATALDO/ROSE

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK		AMOUNT		METHOD
Material	From	To	Sacks or Pounds	
BENTONITE	0	18	450 LBS	OVERBORE

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 128Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1	128	.250	STEEL	☒	☐	☒	☐

Length of Headpipe 5 Length of Tailpipe 3

9. PERFORATIONS/SCREENS

- ☐ Perforations Method _____
☒ Screens Screen Type SS

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
128	133	50	1	6	STEEL	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

10 ft. below ground Artesian pressure _____ lb.Depth flow encountered 130 ft. Describe access port or control devices: _____49N 1W 34

11. WELL TESTS:

- ☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
25			2 HRS

Water Temp. COLD Bottom Hole Temp COLDWater Quality test or comments: GOODDepth first Water encountered 74

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Water	
10	0	2	Top Soil	☐ Y	☒ N
10	2	18	Brown Clay	☐ Y	☒ N
8	18	45	Broken Shale & Brown Clay	☐ Y	☒ N
8	45	65	Gray Clay	☐ Y	☒ N
8	65	75	Broken Shale & Brown Clay	☒ Y	☐ N
8	75	116	Brown Clay	☐ Y	☒ N
8	116	135	Broken Shale w/ Brwn.Gry Clay Seems	☒ Y	☐ N

RECEIVED

AUG 07 2007

IDWR/North

Completed Depth 135 (Measurable)Date: Started 6/28/2007 Completed 6/29/2007

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O WellService, Inc. Firm No. 448Firm Official Steve R. Kern Date 7-5-07

and

Supervisor or Operator Bob Kern Date 6/29/07

BOB KERN

(Sign Once If Firm Official and Operator)

BEELER PIN 49N01W-34-5425

