1238-7
.8
Starships Consulting and Management Services

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by_____
Twp____Rge____Sec____
____1/4____1/4____1/4
Lat: : : Long: : :

1. WELL TAG NO. D10364
Drilling Permit No: _____
Other IDWR No. _____

2. OWNER **Well Number:** 908
Name KELLY, ZANE
Address 17401 E KILLARNEY LAKE
City CATALDO State ID Zip 83810

3. LOCATION OF WELL by legal description
sketch map location must agree with written location

N / W / E / S — X

Twp. 48 ☑ North or ☐ South
Rge. 02 ☐ East or ☑ West
Sec. 11 ____ 1/4 SE 1/4 NE 1/4
Gov't Lot ____ County KOOTENAI
Lat: : : Long: : :
Address of Well Site SAME AS ABOVE
City CATALDO
(Give at least name of road + Distance to Road or Landmark)
Lt. ____ Blk. ____ Sub. Name _____

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☑ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
BENTONITE	0	18	3.5 BAGS	OVERBORE

Was drive shoe used? ☐ Y ☑ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	18	.250	STEEL	☑	☐	☑	☐
4	-8	243	.160	PVC	☐	☑	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☐ Perforations Method SKILLSAW
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
203	243	1/8X4	170	4	PVC	☐	☑

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
70 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: _____

11. WELL TESTS:
☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
30-40 GPM		243	2 HRS

Water Temp. ____ Bottom Hole Temp ____
Water Quality test or comments: _____
Depth first Water encountered 235

12. LITHOLOGIC LOG:(Describe repairs or abandonment

Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Water Y	Water N
8	0	235	Shale Dark Gray Hard	☐	☑
6	235	243	Shale Broken Gray W/Water 30-40 GP	☑	☐

Completed Depth 243' (Measurable)
Date: Started 7/29/99 Completed 7/29/99

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H20 WellService, Inc. Firm No. 448
Firm Official _____ Date 7/29/99
and
Supervisor or Operator _____ Date 7/29/99
(Sign Once if Firm Official and Operator)
(Louie Hamer)