

Office Use Only  
Inspected by \_\_\_\_\_  
Twp \_\_\_\_\_ Rge \_\_\_\_\_ Sec \_\_\_\_\_  
\_\_\_\_\_ 1/4 \_\_\_\_\_ 1/4 \_\_\_\_\_ 1/4  
Lat: : : Long: : :

2. OWNER:  
Name Don + Lillianne Hess  
Address 2852 Harrison Ave  
City Coeur D'Alene State ID Zip 83814

Sketch map location must agree with written location.

N  
 W E S  
 Twp. 48 North ☒ or South ☐  
 Rge. 4 East ☐ or West ☐  
 Sec. 1  $\frac{1}{4}$   $\frac{1}{4}$   $\frac{1}{4}$   $\frac{1}{4}$   
 Gov't Lot \_\_\_\_\_ 10 acres 40 acres 160 acres  
 County Kootenai  
 Lat. : : Long. : :  
 Address of Well Site Martin Point  
 City Harrison  
 Rdo. \_\_\_\_\_  
 (Give at least name of road + Distance to Road or Landmark)

| Lt. | Blk. | Sub. | Name |
|-----|------|------|------|
|-----|------|------|------|

☒ Domestic    ☐ Municipal    ☐ Monitor    ☐ Irrigation  
☐ Thermal    ☐ Injection    ☐ Other

☒ New Well ☐ Modify ☐ Abandonment ☐ Other \_\_\_\_\_

☒ Air Rotary    ☐ Cable    ☐ Mud Rotary    ☐ Other \_\_\_\_\_

| SEAL/FILTER PACK |      |    | AMOUNT          | METHOD           |
|------------------|------|----|-----------------|------------------|
| Material         | From | To | Sacks or Pounds |                  |
| Bentonite        | 0    | 50 | 275 X           | Pour Around Pipe |
|                  |      |    |                 |                  |

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 98'  
Was drive shoe seal tested? ☒ Y ☐ N How? AIR

| Diameter | From | To  | Gauge | Material | Casing                              | Liner                    | Welded                              | Threaded                 |
|----------|------|-----|-------|----------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 6"       | +2   | -98 | 250   | Steel    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
|          |      |     |       |          | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
|          |      |     |       |          | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

Length of Headpipe \_\_\_\_\_ Length of Tailpipe \_\_\_\_\_

Perforations Method none

Screens Screen Type

| From | To | Slot Size | Number | Diameter | Material | Casing                   | Liner                    |
|------|----|-----------|--------|----------|----------|--------------------------|--------------------------|
|      |    |           |        |          |          | <input type="checkbox"/> | <input type="checkbox"/> |
|      |    |           |        |          |          | <input type="checkbox"/> | <input type="checkbox"/> |
|      |    |           |        |          |          | <input type="checkbox"/> | <input type="checkbox"/> |

55' ft. below ground Artesian pressure \_\_\_\_\_ lb.  
Depth flow encountered 62' ft. Describe access port or  
control devices: well cap

48N 4W 1

☐ Pump    ☐ Bailer    ☐ Air    ☐ Flowing Artesian

| Yield gal./min. | Drawdown | Pumping Level | Time |
|-----------------|----------|---------------|------|
| 100 gal +       | Airlift  | From 100'     |      |
|                 |          |               |      |
|                 |          |               |      |

Water Temp. 50° Bottom hole temp. \_\_\_\_\_

Water Quality test or comments: Clear no odor

Depth first Water Encounter 62

## 12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

[illegible]

~~RECEIVED~~

~~JAN 24 1973~~

IDWR North

Completed Depth 100 (Measurable)

Date: Started 11-26-02 Completed 12-2-02

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name All-Ways Drilling Inc. Firm No. 510

Firm Official Paul E. Wolf Date 6-27-02

and

Driller or Operator Alvin Corbis Date 12-27-02

(Sign once if Firm Official & Operator)