

RECEIVED

CORRECTED REPORT

Form 2 DEC 10 2001
11/97

IDAHO DEPARTMENT OF WATER RESOURCES

IDWR/North

WELL DRILLER'S REPORT

1. WELL TAG NO. D D0012824

DRILLING PERMIT NO. _____

Other IDWR No. _____

2. OWNER:

Name Richard Dewey
Address P.O. Box 4218
City Seattle State WA Zip 98104

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N		Twp. <u>47</u>		North ☒ or South ☐	
W		Rge. <u>4</u>		East ☐ or West ☒	
E		Sec. <u>4</u>		1/4 <u>N/E</u> 1/4 <u>S/W</u> 1/4	
S		Gov't Lot <u>1</u>		County <u>Adams</u>	
		Lat: _____		Long: _____	
		Address of Well Site <u>Cottonwood Rd.</u>		City <u>Worley</u>	
		<u>Tuley Lane</u>			

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK		AMOUNT		METHOD
Material	From	To	Sacks or Pounds	
Bentonite	0	50	1456	Pour Mud Pipe

Was drive shoe used? ☒ N Shoe Depth(s) 78Was drive shoe seal tested? ☒ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	-78	225	Steel	☒	☐	☒	☐
4"	-5	-125	160	PVC	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☒ Perforations Method Drill

Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
185	105	1"	16	4"	PVC	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

4/2 ft. below ground Artesian pressure _____ lb.

 Depth flow encountered 78' ft. Describe access port or control devices: Well Cap

Office Use Only	
Inspected by	<u>RFD</u>
Twp	<u>47N Rge 4E Sec 4</u>
	<u>1/4 NW 1/4 NE 1/4</u>
Lat: _____	Long: _____

11. WELL TESTS:

☐ Pump ☐ Baller ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
<u>70 gpm</u>	<u>Air lift from 125'</u>		

Water Temp. 48°

Bottom hole temp. _____

Water Quality test or comments: Clear no odorDepth first Water Encounter 78'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8"	0	4	Sand & Gravel		
	4	53	Basalt - Gray - Broken		
	53	78	Basalt - Gray		
6"	78	125	Basalt - Gray - Broken w/ water	X	
			<u>70 gpm from 125'</u>		

 Completed Depth 125 (Measurable)
 Date: Started 11-1-01 Completed 11-2-01

13. DRILLER'S CERTIFICATION

We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name All-ways Drilling Inc. Firm No. 510Firm Official Frank Wolfe Date 12-4-01and Driller or Operator Chris Carver Date 11-25-01

(Sign once if Firm Official & Operator)

47N 4W 4
NW NE

FORWARD WHITE COPY TO WATER RESOURCES