

№ 15267



DATE 11/13/03 20

QTY.	ITEM	LIST/LABOR	CHARGE
	Goulds Submersible Pump Model 10L507412		582 00
	5 year Warranty on Pump		
	42' - 1" galv drop Pipe		77 28
	Paid 2722		
	Lump		



LARRY BLAIR Potlatch (208)875-0268
St. Maries (208)245-4108

SCANNED
JAN 25 2011

If using credit card for payment, add 4.5%.

TERMS: NET 10 DAYS FROM INVOICE DATE.

A finance charge of 1 1/2% (21% corresponding annual percentage rate, \$1.00 minimum) will be charged on all unpaid accounts.

	SUBTOTAL		659	20
	PUMP TRUCK/LABOR		180	00
	SUBTOTAL			
	S. SALES TAX	Id	42	11
	TOTAL		881	31

WELL DRILLER'S REPORT

State law requires that this report be filed with the Director, Department of Water Administration within 30 days after the completion or abandonment of the well.

1. WELL OWNER

Name Dr. W. H. Key, Manager
Address 193 - Bay View Road, Waco, Texas
Owner's Permit No. _____

2. NATURE OF WORK

☒ New well ☐ Deepened ☐ Replacement
☐ Abandoned (describe method of abandoning)

3. PROPOSED USE

☒ Domestic ☐ Irrigation ☐ Test ☐ Other (specify type)

☐ Municipal ☐ Industrial ☐ Stock ☐ Waste Disposal or Injection

4. METHOD DRILLED

☐ Cable ☒ ~~Rotary~~ ☐ Dug ☐ Other

5. WELL CONSTRUCTION

Diameter of hole 6 inches Total depth 140' feet
Casing schedule: ☐ Steel ☐ Concrete

Thickness	Diameter	From	To
<u>250</u> inches	<u>6</u> inches	+ <u>1</u> feet	<u>71</u> feet
<u>280</u> inches	<u>5</u> inches	- <u>10</u> feet	<u>100</u> feet
_____ inches	_____ inches	_____ feet	_____ feet
_____ inches	_____ inches	_____ feet	_____ feet
_____ inches	_____ inches	_____ feet	_____ feet

Was a packer or seal used? ☐ Yes ☒ No
 Perforated? ☐ Yes ☒ No
 How perforated? ☐ Factory ☐ Knife ☐ Torch
 Size of perforation, _____ inches by _____ inches

Size of perforation _____ inches by _____ inches

Number	From	To
_____ perforations	_____ feet	_____ feet
_____ perforations	_____ feet	_____ feet
_____ perforations	_____ feet	_____ feet

Well screen installed? ☐ Yes ☒ No

Manufacturer's name _____

Type _____ Model No. _____

Diameter _____ Slot size _____ Set from _____ feet to _____ feet


Diameter _____ Slot size _____ Set from _____ feet to _____ feet

Gravel packed? ☐ Yes ☒ No Size of gravel _____
Placed from _____ feet to _____ feet

Surface seal depth 21' Material used in seal ☐ Cement grout
☒ Puddling clay ☐ Well cuttings
Sealing procedure used ☐ Slurry pit ☐ Temporary surface casing
☐ Overbore to seal depth

6. LOCATION OF WELL

Sketch map location must agree with written location.



Subdivision Name _____

Lot No. _____ Block No. _____

County Bernie

NW 1/4 NW 1/4 Sec. 17 T. 46 N/S. R. 2 E/W

7. WATER LEVEL

Static water level _____ feet below land surface
Flowing? ☐ Yes ☐ No G.P.M. flow _____
Temperature _____ ° F. Quality _____
Artesian closed-in pressure _____ p.s.i.
Controlled by ☐ Valve ☐ Cap ☐ Plug

8. WELL TEST DATA

☐ Pump ☐ Bailer ☒ Other

Discharge G.P.M.	Draw Down	Hours Pumped
------------------	-----------	--------------

9. LITHOLOGIC LOG

Hole Diam.	Depth		Material	Water	
	From	To		Yes	No
6	1	2	Top Soil		X
	2	5	CLAY		X
	5	14	SAND		X
	14	26	CLAY		X
	26	33	BROKEN BASALT		X
	33	45	CLAY		X
	45	71	BROKEN BASALT		X
	71	140	BROKEN BASALT	X	
			Water 120 ft		

10.

Work started 3-22-75 finished 4-1-75

11. DRILLERS CERTIFICATION

Firm Name J. J. ... Co. Firm No. ...

Address 1201 72nd St. S.W. Date 3/3/88

Signed by (Firm Official) _____

and
(Operator) _____

SCANNED
JAN 25 2011

PLAT MAP ADDENDUM

File No. 20020201

Borrower Chester & Shirley Slade

Property Address 87560 Highway 3 North

City St. Maries


County Benewah

State Idaho

Zip Code 83861

Lender/Client Bank of Latah

Address P.O. Box 40, Latah, Washington 99018



SCANNED
JAN 25 2011