

RECEIVED

Form 11/79 1018-7-09 1993

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

076496

Office Use Only		
Inspected by		
Twp	Rge	Sec
1/4	1/4	1/4
Lat	Long	
☒ Air	☐ Flowing Artesian	

IDWR/North

1. WELL TAG NO. D 10185

DRILLING PERMIT NO. 93-99-N-2

Other IDWR No. _____

2. OWNER: Nathan
Name Sharon Peters
Address 6323 E. Grouse Rd
City Chattahoochee State Idaho Zip 99003

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N		Twp. <u>4E</u>		North ☒ or South ☐	
E		Rge. <u>5</u>		East ☐ or West ☒	
S		Sec. <u>20</u>		1/4 <u>SW</u> 1/4 <u>SW</u> 1/4 <u>SW</u>	
W		Gov't Lot _____		County <u>Benzon</u>	
E		Lat: _____		Long: _____	
S		Address of Well Site <u>Freight Rd. & 4th</u>		City <u>Chattahoochee</u>	

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT		METHOD
Material	From	To	Sacks or Pounds		
Bentonite	0	153	4000		Pour dry

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 153

Was drive shoe seal tested? ☒ Y ☐ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	153	.250	Steel	☒	☐	☒	☐
4"	80	200	.100	PVC	☐	☒	☐	☐

Length of Headpipe N/A Length of Tailpipe N/A

9. PERFORATIONS/SCREENS

Perforations Method Drill
Screens Screen Type N/A

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
140	180	1/4"	60	4"	PVC	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

147 ft. below ground Artesian pressure N/A lb.
Depth flow encountered 170 ft. Describe access port or control devices: Well Cap

11. WELL TESTS:

- ☐ Pump ☐ Bailor

Yield gal/min	Drawdown	Pumping Level	Time
50			1 hr

Water Temp. Cold Bottom hole temp. Cold

Water Quality test or comments: Clear

Depth first Water Encounter 170

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8"	0	19	Top soil		☒
8"	19	24	Shale broken		☒
8"	24	84	Clay red		☒
8"	84	117	Clay tan w/ gravel		☒
8"	117	135	Clay red		☒
8"	135	153	Shale soft grey		☒
6"	153	170	Shale soft grey		☒
6"	170	200	Granite broken		☒

Completed Depth 200' (Measurable)
Date: Started 7-1-99 Completed 7-1-99

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Always Drilling Inc. Firm No. 510

Firm Official Stanley Walker Date 7/8/99

and Driller or Operator W.D.C. Date 7-2-99

(Sign once if Firm Official & Operator)

46N 5W 20

FORWARD WHITE COPY TO WATER RESOURCES