

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT
RECEIVED

Office Use Only			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat		Long	

1. WELL TAG NO. D0017189

Drilling Permit No: _____

Other IDWR No. 769120

MAY 28 2001

WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

2. OWNER

Name Walt Larson

Address 3134 Spirt Lake Cut Off Road

City Spirit Lake State ID Zip 83869

3. LOCATION OF WELL by legal description

sketch map location must agree with written location

N			
S			

Twp. 54 ☒ North or ☐ South

Rge. 04 ☐ East or ☒ West

E Sec. 17 1/4 NW 1/4 NW 1/4

Gov't Lot _____ County BONNER

Lat: _____ Long: _____

Address of Well Site 3134 Spirt Lake Cut O
City Spirit Lake

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation

☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK		AMOUNT		METHOD
Material	From	To	Sacks or Pounds	
BENTONITE	0	38	36 bags	overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 38

Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	-2	38	.280	steel	☒	☐	☒	☐
4	-25	125	.160	pvc	☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☒ Perforations Method skill saw

☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
85	125	1/8x6	600	4	pvc	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

55 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

54N 4W 17

Yield gal./min.	Drawdown	Pumping Level	Time
estimate 15-20			1 hour

Water Temp. cold Bottom Hole Temp cold

Water Quality test or comments: clear

Depth first Water encountered 75

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

				Water	
Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Y	N
10	0	2	Topsoil	☐	☒
10	2	86	Coarse gravel	☐	☒
10	26	38	Granite broken	☐	☒
6	38	51	Granite black w/white	☐	☒
6	51	83	Granite green/white/black	☒	☐
6	83	106	Granite white w/black	☐	☒
6	106	110	Granite green/grav/broken	☒	☐
6	110	125	Granite black w/white	☐	☒

RECEIVED

JUL 30 2001

Department of Water Resources

Completed Depth 125 (Measurable)
Date: Started 5/24/01 Completed 5/25/01

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O WellService, Inc. Firm No. 448

Firm Official [Signature] Date 5-25-01

and [Signature] Date 5-25-01

Supervisor or Operator [Signature] Date _____

(Sign Once if Firm Official and Operator)

