

IDWR TAG #:

LEGAL DESCRIPTION:

DATE PHOTO TAKEN:

AGENT:

CLAIM OR WATER RIGHT NUMBER:

Tns 13S; Rng 25E; Sec 14; SW¼NW¼NE¼ B.M.

06-29-95

KELLY K CHRISTENSEN

A43-00370

This photo is looking south across Blacksmith Creek and the point where an unnamed stream joins Blacksmith Creek. That stream roughly parallels Highway 77 from near Connor Summit to this point. The normal channel swings through and to the left of the brush on the left. A GPS reading was taken at this point but no site tag was placed at this location as there was no permanent structure to attach the tag to.

This is the northern most point of diversion of three from Blacksmith Creek.



IDWR TAG #:

LEGAL DESCRIPTION:

DATE PHOTO TAKEN:

AGENT:

CLAIM OR WATER RIGHT NUMBER:

Tns 13S; Rng 25E; Sec 11; SW $\frac{1}{4}$ SW $\frac{1}{4}$ B.M.

06-29-95

KELLY K CHRISTENSEN

A43-00370

This photo shows the eastern most spring of the Mahogany Springs System. You are looking east across the ditch and spring water. The spring is coming in from the left and the ditch runs along the right. I measured 0.50 cfs at this point which includes the output of all three springs.

GPS SITE

