Form 238-7
3/95

RECEIVED
OCT 0 1 1997
NORTHERN REGION

POSTED

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

096331

Office Use Only
Inspected by _____
Twp____ Rge____ Sec____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 94 - 97 - N - 31 - ____
Other IDWR No. IDWR D 0003291

2. OWNER:
Name Merton Steward
Address P.O. Box 474
City Pinehurst State ID Zip 83850

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 49 North ☒ or South ☐
Rge. 2 East ☒ or West ☐
Sec. 29, ____ 10 acres 1/4 NW 40 acres 1/4 SE 160 acres 1/4
Gov't Lot ____ County ____
Lat: : : Long: : :
Address of Well Site Bear Creek City Enaville
(Give at least name of road + Distance to Road or Landmark)
Lt.____ Blk.____ Sub. Name____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	25	200#	overbore

Was drive shoe used? ☒Y ☐N Shoe Depth(s) 25
Was drive shoe seal tested? ☐Y ☐N How?____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	25	.25	steel	☒	☐	☐	☐
4"	-13	83	160	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe____ Length of Tailpipe____

9. PERFORATIONS/SCREENS
☒ Perforations Method 1/8x4" saw cut
☐ Screens Screen Type____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
48 ft. below ground Artesian pressure ____ lb.
Depth flow encountered 72 ft. Describe access port or control devices:____

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
15-18			

Water Temp. ____ Bottom hole temp. ____
Water Quality test or comments: ____
Depth first Water Encountered 72

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8"	0	16	Sand, brown, med fine		x
	16	56	Shale, tan/grey, soft brk		x
	56	72	Shale, grey, med hard		x
	72	85	Shale, grey brn, soft brk	x	

Completed Depth 85' (Measurable)
Date: Started 9/04/97 Completed 9/05/97

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name McCarty & Associates Firm No. 586
Firm Official Brett McCarty Date 9-8-97
and
Supervisor or Operator____ Date____
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES

NWSE 29 49N 2E

SCANNED
NOV 13 2013