

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	:	Long:	:

1. WELL TAG NO. D 0056389
 DRILLING PERMIT NO. _____
 Water Right or Injection Well No. _____

2. OWNER:
 Name Cathy Kendrick
 Address 1410 Lincoln Way
 City Coeur d'Alene State Id. Zip 83814

3. LOCATION OF WELL by legal description:
 You must provide address or Lot, Blk, Sub. or Directions to well.
 Twp. 50 North ☒ or South ☐
 Rge. 04 East ☒ or West ☐
 Sec. 31 1/4 SE 1/4 NW 1/4
 Gov't Lot _____ County Shoshone
 Lat: _____ Long: _____
 Address of Well Site moose tracks Lane
 City Prichard
 (Give at least name of road + Distance to Road or Landmark)
 Lt. 13 Blk. _____ Sub. Name Cedars on the
North Fork

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:
☐ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
<u>Bentonite</u>	<u>0</u>	<u>19</u>	<u>250 lbs</u>	<u>poured</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 36'
 Was drive shoe seal tested? ☒ Y ☐ N How? water

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6"</u>	<u>+3</u>	<u>-36</u>	<u>250</u>	<u>Steel</u>	☒	☐	☒	☐

Length of Headpipe N/A Length of Tailpipe _____
 Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method N/A
 Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. FILTER PACK N/A

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

15 ft. below ground Artesian pressure _____ lb.
 Depth flow encountered _____ ft. Describe access port or control devices:
6" Bolted WELL Cap

12. WELL TESTS:

☐ Pump	☒ Bailer	☐ Air	☐ Flowing Artesian
Yield gal./min.	Drawdown	Pumping Level	Time
<u>Approx 25</u>			

Water Temp. Cool Bottom hole temp. Cool
 Water Quality test or comments: Good

Depth first Water Encounter 17'

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>10</u>	<u>0</u>	<u>19</u>			
<u>6</u>	<u>19</u>	<u>36</u>			
	<u>0</u>	<u>3</u>	<u>Top Soil</u>		☒
	<u>3</u>	<u>13</u>	<u>Boulders, Gobbles, Gravel</u>		☒
	<u>13</u>	<u>36</u>	<u>Sand, Gravel</u>	☒	



RECEIVED

AUG 05 2009

IDWR/North

Completed Depth 36' (Measurable)

Date: Started 7-14-09 Completed 7-20-09

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Valley Drilling Co. Firm No. 683

Principal Driller Wayne Miller Date 7-23-09

Driller or Operator II _____ Date _____

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
 Operator I must have signature of Driller/Operator II.