Form 238-7
11/97

# IDAHO DEPARTMENT OF WATER RESOURCES
# WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

POSTED

**1. WELL TAG NO.** D 0022933
DRILLING PERMIT NO. 787-44 -
Other IDWR No.

**2. OWNER:**
Name Dave Asher
Address 1059 Parkside Rd
City Plummer State ID Zip 83851

**3. LOCATION OF WELL by legal description:**
Sketch map location must agree with written location.

N / W / E / S

Twp. 46 North ☑ or South ☐
Rge. 4 East ☐ or West ☑
Sec. 13, ____ 1/4 S/E 1/4 N/E 1/4
(10 acres / 40 acres / 160 acres)
Gov't Lot ____ County Benewah
Lat: : : Long: : :
Address of Well Site 1059 Parkside Rd City
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name

**4. USE:**
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

**5. TYPE OF WORK** check all that apply (Replacement etc.)
☐ New Well ☑ Modify ☐ Abandonment ☐ Other

**6. DRILL METHOD**
☑ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

**7. SEALING PROCEDURES**

| SEAL/FILTER PACK Material | From | To | AMOUNT Sacks or Pounds | METHOD |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |

Was drive shoe used? ☐Y ☐ N Shoe Depth(s)
Was drive shoe seal tested? ☐ Y☐ N How?

**8. CASING/LINER:**

| Diameter | From | To | Gauge | Material | Casing | Liner | Welded | Threaded |
|---|---|---|---|---|---|---|---|---|
| | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |

Length of Headpipe ____ Length of Tailpipe ____

**9. PERFORATIONS/SCREENS**
Perforations Method Drill
Screens Screen Type

| From | To | Slot Size | Number | Diameter | Material | Casing | Liner |
|---|---|---|---|---|---|---|---|
| -5 | -150 | 1" | | 4" | PVC | ☐ | ☑ |
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |

**10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:**
40 ft. below ground Artesian pressure ____ lb.
Depth flow encountered 112 ft. Describe access port or control devices: w-cap

46N 4W 13

**11. WELL TESTS:**
☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

| Yield gal./min. | Drawdown | Pumping Level | Time |
|---|---|---|---|
| 20 | air lift from | 150 | 30 min |
| | | | |
| | | | |

Water Temp. 47 Bottom hole temp.
Water Quality test or comments: Clear and no odor
Depth first Water Encounter 112

**12. LITHOLOGIC LOG:** (Describe repairs or abandonment)

| Bore Dia. | From | To | Remarks: Lithology, Water Quality & Temperature | Water Y | Water N |
|---|---|---|---|---|---|
| 6" | -5 | -150 | Hard Basalt | ✓ | |
| | | | RECEIVED | | |
| | | | OCT 24 2002 | | |
| | | | IDWR-North | | |
| | | | Reamed From | | |
| | | | -20 to -70 | | |
| | | | Drilled From -70 to 150 | | |

Completed Depth 150 (Measurable)
Date: Started 10/17/02 Completed 10/18/02

**13. DRILLER'S CERTIFICATION**
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name All-Way Drilling INC Firm No. 510
Firm Official Stanley K Wolfe Date 10/18/02
and
Driller or Operator Donald K Miller Date 10/18/02
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES