Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 0022655
DRILLING PERMIT NO. 83988
Other IDWR No. _____

POSTED

2. OWNER:
Name Ruben Akre
Address Hwy 2
City Priest River State Id. Zip 83856

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 54 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 7, ____ 1/4 SE 1/4 NW 1/4 (10 acres / 40 acres / 160 acres)
Gov't Lot ____ County Bonner
Lat: : : Long: : :
Address of Well Site Roberts Rd
City Blanchard
Hwy 41 (Give nearest name of road + Distance to Road or Landmark)
Lt. 1 Blk. 2 Sub. Name AKRE Acres

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☐ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT (Sacks or Pounds)	METHOD
TempCasing	0	18	5	

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1	103	250	Steel	☒	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
Perforations Method pull back Johnson
Screens Screen Type Telescoping

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
103	108	30		6"	SS	☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
25 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: _____

54N 5W 7

11. WELL TESTS: ☐ Pump ☒ Bailer ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
10+	1'	76'	1hr

Water Temp. Cold Bottom hole temp. _____
Water Quality test or comments: Good
Depth first Water Encounter 90'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	18	Top Soil, Fine Sand		X
6	18	30	Sand		X
6	30	80	Course Sand, gravel		X
6	80	100	Course Sand	X	
6	100	108	Coarse Sand	✓	

RECEIVED
SEP 23 2002
IDWR North

Completed Depth 108 (Measurable)
Date: Started 8-20-02 Completed 8-26-02

SCANNED
JAN 10 2014

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Carl Pitts & Sons Firm No. 168
Firm Official Steve Pitts Date 8/26/02
and
Driller or Operator Steve Pitts Date 8/26/02
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES