RECEIVED

JUL 06 1999

Form 238-3
11/97

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT 076900

IDWR/North

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 5982
DRILLING PERMIT NO. 96-99-N-77
Other IDWR No. _____

2. OWNER:
Name J Hank Hester
Address 1826 Hay Road
City Priest River State ID Zip 83856

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

POSTE

N / W / E / S

Twp. 54 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 15, SE 1/4 (10 acres) NW 1/4 (40 acres) SW 1/4 (160 acres)
Gov't Lot ____ County Bonner
Lat: : : Long: : :
Address of Well Site Saragosa Road
City Blanchard
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT (Sacks or Pounds)	METHOD
Bentonite	0	20	7	overbored

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 220'
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1½	220	.250	Steel	☒	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
Perforations Method Air Perforator
Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
190	210	⅛x1	60	6	Steel	☒	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
160 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
30			4 Hours

Water Temp. _____ Bottom hole temp. _____
Water Quality test or comments: _____
Depth first Water Encounter 160

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	11	Soil and Gravel		X
8	11	35	Sand and Gravel		X
6	35	90	Sand		X
6	90	160	Gravel		X
6	160	175	Sand	X	
6	175	190	Sand and Gravel	X	
6	190	220	Gravel	X	
			10' of Gravel in Bottom		

Completed Depth 210' (Measurable)
Date: Started 5-3-99 Completed 5-6-99

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

SCANNED
JAN 20 2014

Company Name Hester Well drilling Firm No. 528
Firm Official _____ Date 5-11-99
and
Driller or Operator C. Mark Hester Date 5-11-99
(Sign once if Firm Official & Operator)

54N 5W 15

FORWARD WHITE COPY TO WATER RESOURCES