

RECEIVED

Use Typewriter
or
Ball Point Pen

OCT 24 1994

NORTHERN REGION
IDWR

Other IDWR No.

2. OWNER: **WILMA KELLEY SPEED**
Name

Name _____
Address 2124 E JANICE WAY
City PHOENIX State AZ Zip 85022-4029

Sketch map location must agree with written location.


 Twp. 54 North ☒ or South ☐
 Rge. 05 East ☐ or West ☒
 Sec. 13 1/4 SW 1/4 SE 1/4
 Gov't Lot _____ 10 acres _____ 40 acres _____ 160 acres
 County Bonner

Address of Well Site

City.

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

☒ New Well ☐ Modify or Repair ☐ Replacement ☐ Abandonment

☐ Mud Rotary ☒ Air Rotary ☐ Cable ☐ Other _____

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
Bentonite	0	25	8 sacks	Crumbles

Was drive shoe used? ☒ YES ☐ NO

Was drive shoe seal tested? Y ☐ N ☒ How?

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	25	.250	Steel	☒	☐	☒	☐
4"	-10	590	.160	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☒ Perforations	Method	Saw	Cut
--	--------	-----	-----

☐ Screens	Screen Type
----------------------------------	-------------

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
550	590	1/16	65	4"	PVC	☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

365 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
2			2 hrs

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments:

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	25	CLAYS LIGHT BROWN SOFT		X
6	25	26	GRANITE BLACK M-HARD		X
6	26	39	GRANITE DECOMPOSED BROWNISH		X
6	39	63	GRANITE BLACK HARD		X
6	63	70	GRANITE GREEN & WHITE HARD		X
6	70	83	GRANITE BLACK HARD		X
6	83	86	GRANITE BLACK FRACTURED		X
6	86	108	GRANITE BLACK HARD		X
6	108	117	GRANITE BLACK FRACTURED		X
6	117	130	GRANITE BLACK HARD		X
6	130	135	GRANITE BLACK FRACTURED		X
6	135	170	GRANITE BLACK HARD		X
6	170	175	GRANITE BLACK FRACTURED		X
6	175	180	GRANITE W/CLAY LENSES LT-BROWN		X
6	180	203	GRANITE SALT & PEPPER HARD		X
6	203	206	GRANITE SALT & PEPPER FRACTURED	XD	
6	206	224	GRANITE SALT & PEPPER HARD		X
6	224	227	GRANITE GREEN WHITE FRACTURED		X
6	227	240	GRANITE BLACK M-HARD		X
6	240	245	GRANITE BLACK FRACTURED		X
6	245	310	GRANITE SALT & PEPPER HARD		X
6	310	315	GRANITE SALT & PEPPER FRACTURED		X
6	315	380	GRANITE SALT PEPPER HARD		X
6	380	382	GRANITE SALT PEPPER FRACTURED		X
6	382	420	GRANITE SALT PEPPER HARD		X
6	420	460	GRANITE SALT PEPPER FRACTURED		X
6	460	498	GRANITE SALT PEPPER HARD		X
6	498	506	GRANITE SALT PEPPER FRACTURED		X
6	506	545	GRANITE SALT & PEPPER HARD		X
6	545	560	GRANITE SALT PEPPER FRACTURED		X
6	560	590	GRANITE SALT & PEPPER M-HARD		X
MICROFILMED					

Completed 10/12/94 (Measurable)
Date: Started 10/11/94

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name **H2O WELL SERVICE INC** Firm No. **448**

Firm Official John W. Hahn Date 10-17-94

and
Supervisor or Operator Mark J. Lee Date 10/16/94

(Sign once if Firm Official & Operator)

SW SE 13 54N 5W

FORWARD WHITE COPY TO WATER RESOURCES