

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT1. WELL TAG NO. D 0044874DRILLING PERMIT NO. 840152

Water Right or Injection Well No. _____

2. OWNER:

Name Dan Ford & Jodi Ford
Address P.O. Box 942
City Spirit Lake State Id. Zip 83869

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub, or Directions to well.

Twp. 54 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 22 1/4 NE 1/4 NE 1/4
Gov't Lot _____ County BonnerLat: _____ Long: _____
Address of Well Site Blanchard Cut-off rd. E. of
Walker City Blanchard
(Give at least name of road - Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
<u>Bentonite</u>	<u>0</u>	<u>20</u>	<u>200 lbs</u>	<u>over bore</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 218'Was drive shoe seal tested? ☒ Y ☐ N How? Air Pressure

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6"</u>	<u>+1</u>	<u>-218</u>	<u>250</u>	<u>Steel</u>	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method N/AScreen Type & Method of Installation N/A

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. FILTER PACK N/A

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

120 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

6" Bolted Well Cap54N 5W 22

Office Use Only

Well ID No. _____

Inspected by _____

Twp _____ Rge _____ Sec _____

1/4 1/4 1/4

Lat: _____ Long: _____

12. WELL TESTS:

☐ Pump☐ Bailor☒ Air☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
<u>Approx. 100</u>			

Water Temp. CoolBottom hole temp. CoolWater Quality test or comments: GoodDepth first Water Encounter 120'

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>8"</u>	<u>0</u>	<u>218</u>			
	<u>0</u>	<u>56</u>	<u>Gravel Cabbies & Course Sand</u>		
	<u>56</u>	<u>64</u>	<u>Gravel Cabbies & Boulders</u>		
	<u>64</u>	<u>108</u>	<u>Course Sand & pea gravel</u>		
	<u>108</u>	<u>148</u>	<u>Gravel & Small Boulders</u>		
	<u>148</u>	<u>175</u>	<u>Course sand</u>		
	<u>175</u>	<u>185</u>	<u>Blue Sandy Clay</u>		
	<u>185</u>	<u>200</u>	<u>Course Sand & pea gravel</u>	☒	
	<u>200</u>	<u>218</u>	<u>Gravel & Course Sand</u>	☒	

RECEIVED
JUL 03 2006
IDWR/NorthAQUA DRILLING
& EXPLORATION INC.

PO BOX 2850

HAYDEN, ID 83835-2850

CANNED

JAN 23 2011

Completed Depth 218' (Measurable)Date: Started 6-6-06 Completed 6-7-06

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name AQUA DRILLING & EXPLORATION INC. Firm No. 163Principal Driller Scotty Braun Date _____and Driller or Operator II Wayne Miller Date 6-8-06

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.