Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT 076878

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 5835
DRILLING PERMIT NO. 96-99-N-55
Other IDWR No.

2. OWNER:
Name John Wallace
Address PO Box 35
City Careywood State Id Zip 83809

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

POSTED

N / W / E / S

Twp. 55 North ☒ or South ☐
Rge. 3 East ☐ or West ☒
Sec. 24 ____ 1/4 (10 acres) NE 1/4 (40 acres) SW 1/4 (160 acres)
Gov't Lot ____ County ____
Lat: : : Long: : :
Address of Well Site 106 Bay View Rd
City Careywood
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name ____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD
☐ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	19	8	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) ____
Was drive shoe seal tested? ☐ Y ☒ N How? ____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	0	48	250	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
Perforations Method ____
Screens Screen Type Stainless Steel

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
~~48~~ 54	59	35		6"		☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
5 ft. below ground Artesian pressure — lb.
Depth flow encountered 48 ft. Describe access port or control devices: well Seal

11. WELL TESTS:
☐ Pump ☒ Baller ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
30	20	25	1hr

Water Temp. Cold Bottom hole temp. ✓
Water Quality test or comments: ✓
Depth first Water Encounter 48

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	1	Top Soil		X
8	1	48	Sand & Gravel		X
6	48	59	Pea Gravel	X	

BOB PITTS & SONS
Well Drilling
11986 Baldy Mt. Rd.
Sandpoint ID 83864-8209

RECEIVED
MAY 04 1999
IDWR/North

SCANNED
JAN 28 2014

Completed Depth 58 (Measurable)
Date: Started 4-7-99 Completed 4-8-99

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Bob Pitts & Sons Firm No. 235
Firm Official Bob Pitts Date 4-9-99
and
Driller or Operator ____ Date ____
(Sign once if Firm Official & Operator)

55N 3W 24

FORWARD WHITE COPY TO WATER RESOURCES