RECEIVED
JUL 17 1995
IDWR

Form 238-7
3/95

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

Office Use Only
Inspected by TOK
Twp 54N Rge 3W Sec 21
1/4 NW 1/4 SE 1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 96 - 95 - N - 0061 - 000
Other IDWR No.

2. OWNER:
Name JANICE ABEL
Address W 1830 LAKE FOREST DRIVE
City RATHDRUM State ID Zip 83858

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 54 North [X] or South [ ]
Rge. 03 East [ ] or West [X]
Sec. 21, 1/4 (10 acres) NW 1/4 (40 acres) SE 1/4 (160 acres)
Gov't Lot ____ County BONNER
Lat: : : Long: : :
Address of Well Site
City
(Give at least name of road + Distance to Road or Landmark)
Lt. 001 Blk. 002 Sub. Name KELSO LAKE VIEW

4. USE:
[X] Domestic [ ] Municipal [ ] Monitor [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Other

5. TYPE OF WORK check all that apply (Replacement etc.)
[X] New Well [ ] Modify [ ] Abandonment [ ] Other

6. DRILL METHOD
[X] Air Rotary [ ] Cable [ ] Mud Rotary [ ] Other

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
BENTONITE	0	18	1 SACK	POWDER

Was drive shoe used? [X] Y [ ] N Shoe Depth(s) 18
Was drive shoe seal tested? [ ] Y [ ] N How?

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	18	.250	STEEL	[X]	[ ]	[X]	[ ]
4	-10	325	315	PVC	[ ]	[X]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Length of Headpipe Length of Tailpipe

9. PERFORATIONS/SCREENS
[X] Perforations Method SAWCUT
[ ] Screens Screen Type

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
285	325	1/16	60	4	PVC	[ ]	[X]
						[ ]	[ ]
						[ ]	[ ]

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
185 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices:
NW SE 21 54N 3W

11. WELL TESTS:
[ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
5			1 HR

Water Temp. COLD Bottom hole temp.
Water Quality test or comments: CLEAN
Depth first Water Encountered

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	15	CLAYS COBBLES BROWN SOFT		X
8	15	18	GRANITE WHITE MED		X
6	18	60	GRANITE WHITE HARD		X
6	60	63	GRANITE WHITE GREEN MED		X
6	63	120	GRANITE BLACK HARD		X
6	120	125	GRANITE WHITE GREEN FRACTURED		X
6	125	205	GRANITE BLACK HARD		X
6	205	215	GRANITE WHITE FRACTURED		X
6	215	280	GRANITE BLACK HARD		X
6	280	287	GRANITE WHITE GREEN FRACTURED	X	
6	287	325	GRANITE BLACK WHITE HARD		X
			1x6 WELL SEAL		

MICROFILMED MAR 09 1995
SCANNED JAN 29 2014

Completed Depth 325' (Measurable)
Date: Started 6/19/95 Completed 6/19/95

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O WELL SERVICE INC Firm No. 448
Firm Official [signature] Date 7-14-95
and
Supervisor or Operator Mark L. Lee Date 6-27-95
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES