RECEIVED
OCT 0 1 1997
POSTED

Form 238-7
3/95

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

096330

NORTHERN REGION

Office Use Only
Inspected by _____
Twp.____ Rge.____ Sec.____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT No. 94-97-N-26 -
Other IDWR No. D 0003181

2. OWNER:
Name Merton Steward
Address P. O. Box 474
City Pinehurst State ID Zip 83850

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 49 North ☒ or South ☐
Rge. 2 East ☒ or West ☐
Sec. 29, ____ 1/4 NW 1/4 SE 1/4
(10 acres) (40 acres) (160 acres)
Gov't Lot ____ County ____
Lat: : : Long: : :
Address of Well Site ____
Bear Creek City Enaville
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name ____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
Bentonite	0	25	200#	overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 52
Was drive shoe seal tested? ☐ Y ☒ N How? ____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	52	.250	steel	☒	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
☐ Perforations Method ____
☐ Screens Screen Type ____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
24 ft. below ground Artesian pressure ____ lb.
Depth flow encountered 48 ft. Describe access port or control devices: ____

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
5+			

Water Temp. ____ Bottom hole temp. ____
Water Quality test or comments: ____
Depth first Water Encountered ____

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8"	0	2	Sand w/ clay		x
	2	28	Tan Clay		x
	28	43	Clay, grey		x
	43	46	Clay w/ sand & gravel		x
	46	47	Sand, grey		x
	47	49	Gravel	x	
	49	59	Gravel, large cobbles	x	

Completed Depth 52' (Measurable)
Date: Started 8/27/97 Completed 8/28/97

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name McCarty & Associates Firm No 586
Firm Official [signature] Date 9/2/97
and
Supervisor or Operator ____ Date ____
(Sign once if Firm Official & Operator)

NWSE 29 49N 2E

FOR YOUR WHITE COPY TO WATER RESOURCES