

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

RECEIVED

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat: _____ Long: _____

1. WELL TAG NO. D 10532
DRILLING PERMIT NO. _____ OCT 18 1999
Other IDWR No. 92-99-N-26

2. OWNER: IDWR/North
Name DAVID POOLER
Address 5816 PARK PLACE
City RAZCO State WA Zip 99301

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N
W E
S
Twp. 44 North ☒ or South ☐
Rge. 01 East ☒ or West ☐
Sec. 32 1/4 NW 1/4 SW 1/4
Gov't Lot 05 10 acres 40 acres 160 acres
County BENEFICIAL
Lat: _____ Long: _____
Address of Well Site 1063-C FINN
CREEK ROAD City FERNDWOOD
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT		METHOD
Material	From	To	Sacks or Pounds		
C5 GRANULAR	0'	40'	500 lbs.		OVERDRILL

Was drive shoe used? ☒ N Shoe Depth(s) 155'
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	0'	155'	250	C.S.	☒	☐	☒	☐
4"	155'	550'	160	RVC	☐	☒	☐	☐
			RSI		☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations Method SAW CUT
Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
543	550'	-	21	1/8"	RVC	☐	☒
				1/4"		☐	☐
				3/8"		☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

~ 100 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min.	Drawdown	Pumping Level	Time
~ 2	N.D.	548'	1 HR.

Water Temp. COLD Bottom hole temp. N.D.
Water Quality test or comments: VERY CLEAN WATER
Depth first Water Encounter 205'

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8"	0'	3'	OVERBURDEN		
	3'	23'	BROWN CLAY		
	23'	68'	TAN CLAY		
	68'	71'	ORANGE CLAY		
	71'	93'	LIGHT BROWN CLAY		
	93'	144'	SOFT GREY SHALE		
	144'	155'	MEDIUM HD. GREY SHALE		
	155'	122'	HARD GREY SHALE		
	122'	194'	MEDIUM HD. GREY SHALE		
	194'	321'	HARD GREY SHALE		
	321'	325'	VERY HARD GREY SHALE		
	325'	325'	VERY HARD GREY SHALE		
	325'	371'	MEDIUM HD. GREY SHALE		
	371'	402'	HARD GREY SHALE		
	402'	494'	MEDIUM HD. BLACK SHALE		
	494'	514'	HARD GREY SHALE		
	514'	523'	SOFT LIGHT GREY SHALE		
	523'	550'	HARD GREY SHALE		

Completed Depth 550' (Measurable)
Date: Started 9/16/99 Completed 10/12/99

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

NORTH IDAHO
Company Name WATER WELLS, LLC Firm No. 423

Firm Official [Signature] Date 10/16/99

and Driller or Operator _____ Date _____

(Sign once if Firm Official & Operator)

44N 1E 32

FORWARD WHITE COPY TO WATER RESOURCES