RECEIVED

JUL 09 1999

Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT 076468

IDWR/North

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 10251

DRILLING PERMIT NO. 92-99-N-12

Other IDWR No. _____

2. OWNER:
Name Joel Malynsky
Address 130 E. College
City St. Maries State Id. Zip 83861

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

POSTED

Twp. 46 North ☐ or South ☒
Rge. 2 East ☐ or West ☒
Sec. 27, ____ 1/4 (10 acres) SW 1/4 (40 acres) NE 1/4 (160 acres)
Gov't Lot ____ County Benewah
Lat: : : Long: : :
Address of Well Site Old Rifle Range Rd. City St. Maries
property W. of Residence
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	38	300#	Pour Dry

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 78'
Was drive shoe seal tested? ☒ Y ☐ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	78	.250	Steel	☒	☐	☐	☐
					☐	☐	☐	☐
4"	65	125	160	PVC	☐	☒	☐	☐

Length of Headpipe N/A Length of Tailpipe N/A

9. PERFORATIONS/SCREENS
Perforations Method Drill
Screens Screen Type N/A

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
65	105	14"	60	4"	PVC	☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
20 ft. below ground Artesian pressure N/A lb.
Depth flow encountered 103 ft. Describe access port or control devices: Well Cap

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
60 +			1 hr

Water Temp. Cold Bottom hole temp. Cold
Water Quality test or comments: Clear & clear
Depth first Water Encounter 103

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8"	0	1	Overburden		✓
8"	1	8	Clay grey		✓
8"	8	9	Clay brown		✓
8"	9	38	Basalt broken w/ clay fm		✓
6"	38	78	Basalt broken w/ clay fm		✓
6"	89	103	Clay brown		✓
6"	103	125	Basalt decomposed	✓	

Completed Depth 125 (Measurable)
Date: Started 7-5-99 Completed 7-6-99

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Affordable Drilling Inc. Firm No. 510
Firm Official Stanley Wolf Date 7-6-99
and
Driller or Operator _____ Date 7-6-99
(Sign once if Firm Official & Operator)

46N 2W 27

FORWARD WHITE COPY TO WATER RESOURCES