


WELL DRILLER'S REPORT

RECEIVED

State law requires that this report be filed with the Director, Department of Water Resources within 30 days after the completion or abandonment of the well. NOV 12 1975

1. WELL OWNER Name <u>Larry Croson</u> Address <u>St. Maries</u> Owner's Permit No. <u>92-75-N-11</u>	7. WATER LEVEL Department of Water Resources Northern District Office Static water level <u>40</u> feet below land surface Flowing? ☐ Yes ☒ No G.P.M. flow _____ Temperature <u>60.7</u> ° F. Quality <u>Rock</u> Artesian closed-in pressure _____ p.s.i. Controlled by ☐ Valve ☐ Cap ☐ Plug																						
2. NATURE OF WORK ☒ New well ☐ Deepened ☐ Replacement ☐ Abandoned (describe method of abandoning) _____	8. WELL TEST DATA <u>Air</u> ☐ Pump ☐ Bailer ☒ Other Discharge G.P.M. <u>3-5</u> Draw Down _____ Hours Pumped _____																						
3. PROPOSED USE ☒ Domestic ☐ Irrigation ☐ Test ☐ Other (specify type) _____ ☐ Municipal ☐ Industrial ☐ Stock ☐ Waste Disposal or Injection	9. LITHOLOGIC LOG <table border="1"><thead><tr><th rowspan="2">Hole Diam.</th><th colspan="2">Depth</th><th rowspan="2">Material</th><th rowspan="2">Water Yes/No</th></tr><tr><th>From</th><th>To</th></tr></thead><tbody><tr><td>8</td><td>0</td><td>100</td><td>Gravel & clay</td><td>✓</td></tr><tr><td>6</td><td>100</td><td>125</td><td>Gravel & clay</td><td>✓</td></tr><tr><td>6</td><td>125</td><td>300</td><td>Shale & clay</td><td>✓</td></tr></tbody></table>	Hole Diam.	Depth		Material	Water Yes/No	From	To	8	0	100	Gravel & clay	✓	6	100	125	Gravel & clay	✓	6	125	300	Shale & clay	✓
Hole Diam.	Depth		Material	Water Yes/No																			
	From	To																					
8	0	100	Gravel & clay	✓																			
6	100	125	Gravel & clay	✓																			
6	125	300	Shale & clay	✓																			
4. METHOD DRILLED ☐ Cable ☒ Rotary ☐ Dug ☐ Other																							
5. WELL CONSTRUCTION Diameter of hole <u>6</u> inches Total depth <u>300</u> feet Casing schedule: ☒ Steel ☐ Concrete Thickness Diameter From To <u>1.250</u> inches <u>6</u> inches <u>+1</u> feet <u>62</u> feet <u>1.250</u> inches <u>5</u> inches <u>+1</u> feet <u>94</u> feet ____ inches _____ inches _____ feet _____ feet ____ inches _____ inches _____ feet _____ feet ____ inches _____ inches _____ feet _____ feet Was casing drive shoe used? ☒ Yes ☐ No Was a packer or seal used? ☐ Yes ☒ No Perforated? ☐ Yes ☒ No How perforated? ☐ Factory ☐ Knife ☐ Torch Size of perforation _____ inches by _____ inches Number From To ____ perforations _____ feet _____ feet ____ perforations _____ feet _____ feet ____ perforations _____ feet _____ feet Well screen installed? ☐ Yes ☐ No Manufacturer's name _____ Type _____ Model No. _____ Diameter _____ Slot size _____ Set from _____ feet to _____ feet Diameter _____ Slot size _____ Set from _____ feet to _____ feet Gravel packed? ☐ Yes ☒ No Size of gravel _____ Placed from _____ feet to _____ feet Surface seal depth <u>18</u> Material used in seal ☐ Cement grout ☒ Pudding clay ☒ Well cuttings Sealing procedure used ☐ Sherry pit ☐ Temporary surface casing ☒ Overbore to seal depth																							
6. LOCATION OF WELL Sketch map location must agree with written location.  Subdivision Name _____ Lot No. _____ Block No. _____ County <u>Bennett</u> NW 1/4 SW 1/4 Sec. <u>21</u> T. <u>46</u> N. R. <u>2</u> W.	10. Work started <u>28 Aug 75</u> finished <u>30 Aug 75</u>																						
	11. DRILLERS CERTIFICATION Firm Name <u>Apua Drilling, Inc.</u> Firm No. <u>163</u> Address <u>Box 1002, C.D.O.</u> Date <u>19 Aug 75</u> Signed by (Firm Official) <u>Richard Brown President</u> and (Operator) <u>J.P.C. Jones</u>																						