

RECEIVED

Form 200-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat: _____ Long: _____

1. WELL TAG NO. D 0010533
DRILLING PERMIT NO. 92-99-N-20
Other IDWR No. _____

2. OWNER:
Name Tim Schueller
Address RT 4 Box 94
City ST MARIES State ID Zip 83861

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N
W
E
S
Twp. 45N North ☒ or South ☐
Rge. 1W East ☒ or West ☐
Sec. 20 1/4 N/E 1/4 N/E 1/4
Gov't Lot _____ County BENEFAN 10 acres 40 acres 160 acres
Lat: _____ Long: _____
Address of Well Site 1/4 past Flat Creek
Road Hwy 3 City ST MARIES
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK		AMOUNT		METHOD
Material	From	To	Sack or Pounds	
<u>Bentonite</u>	<u>8</u>	<u>140</u>	<u>10</u>	<u>Poured</u>

Was drive shoe used? ☒ N ☐ Shoe Depth(s) 178

Was drive shoe seal tested? ☒ Y ☐ N How? AIR

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6"</u>	<u>8</u>	<u>178</u>		<u>Steel</u>	☒	☐	☒	☐

Length of Headpipe 12 Length of Tailpipe 178

9. PERFORATIONS/SCREENS

Perforations Method NONE

Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
—	—					☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

100 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 190 ft. Describe access port or control devices: well cap

076477

11. WELL TESTS:

☐ Pump ☐ Bailor

☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
<u>8 gpm</u>			

Water Temp. 56° Bottom hole temp. _____

Water Quality test or comments: Colored

Depth first Water Encounter 180

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>6"</u>	<u>8</u>	<u>80</u>	<u>CLAY yellow</u>		<u>1</u>
<u>6"</u>	<u>80</u>	<u>180</u>	<u>BROWN gray white clay</u>		<u>1</u>
<u>6"</u>	<u>180</u>	<u>190</u>	<u>gray shale</u>	<u>1</u>	
<u>6"</u>	<u>190</u>	<u>427</u>	<u>Hard BGSalt</u>	<u>1</u>	

well owner did
not want to put
liner in yet
8/22/99

Completed Depth 427 (Measurable)

Date: Started 8/18/99 Completed 8/20/99

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Always Drilling Firm No. 510

Firm Official Shane Wolfe Date 9/25/99

and Driller or Operator Craig Smith Date 8/25/99

(Sign once if Firm Official & Operator)

45N 1W 20 FORWARD WHITE COPY TO WATER RESOURCES