



92-10613 2004 IMAGE JACKSON PIN RP45N01W20670CA



6 P 5

(Sign once if Firm Official & Operator)

076493

45N 1W 20 FORWARD WHITE COPY TO WATER RESOURCES

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only

Inspected by _____

Twp _____ Rge _____ Sec _____

5 _____ 1/4 _____ 1/4 _____ 1/4 _____

Lat: : : Long: : :

1. WELL TAG NO. D00/0698
 DRILLING PERMIT NO. 92-99-N-29
 Other IDWR No. _____

2. OWNER:

Name Darren and Jodie Jackson
Address PO Box 388
City Ferrywood State/d Zip 83830

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.



Twp. 45 N North ☐ or South ☒
 Rge. 16 W East ☒ or West ☒
 Sec. 20
 Gov't Lot _____
 Lat: : :
 Long: : :

10 acres 1/4 50 1/4 50 1/4
 County Bernau 40 acres 100 acres

Address of Well Site FIRST enterprises

ON Right on Flat Creek City ST Marks
(Give at least name of road + distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	~~Sack~~ or Pounds	
Bentonite	0	18	4	poured

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 18
Was drive shoe seal tested? ☒ Y ☐ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	0	18		Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe 42 Length of Tailpipe 18

9. PERFORATIONS/SCREENS

Perforations Method N/A
Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
—	—					☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

100 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 125 ft. Describe access port or
control devices: welded 1/4 ST&I plate

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
2 gpm			

Water Temp. N/A Bottom hole temp. _____

Water Quality test or comments: poor

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	10	Soil Hard BGS91T		
6	18	40	Hard Basalt		
6	40	175	BROWN clay	1	
RECEIVED NOV 12 1989 NORTHERN REGION IDWR					
CUSTOMER did NOT want to work with well hole or abandon well used 1/4 steel plate ON TO OF casing Tagged. Casing 00010698					

RECEIVED

NOV 12 1999

NORTHERN REGION
IDMB

CUSTOMER did not want to work with H well hole or abandon well w/ 1/4 steel plate on to of casing Taped. Casing 00010698

Completed Depth 175 (Measurable)
Date: Started 9/28/94 Completed 9/28/99

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Allways Dailine Firm No. 5/6

Firm Official Stanley Webb Date 10/29/87

Driller or Operator Cover Date 9/30/99

(Sign once if Farm Official & Operator)

45N 1W 20 FORWARD WHITE COPY TO WATER RESOURCES