

RECEIVED

11/4/98 db

1-4-99

Form 288-3 1998
1/97

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

77515

Office Use Only

Inspected by

Twp

Rge

Sec

1/4

1/4

1/4

Lat:

Long:

NORTHERN REGION

1. WELL TAG NO. D-000 5339

DRILLING PERMIT NO. 92-98-N-20


Other IDWR No.

2. OWNER

Name Robert + Moore
Address 2077 Boulder meadow
City Oak Harbor State WA Zip 98277

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.



Twp. 44 North ☒ or South ☐
 Rge. 1 East ☐ or West ☒
 Sec. 18 NW 1/4 - 1/4
 Gov't Lot 25 County Benewah
 Lat: Long:
 Address of Well Site 1st of Hwy
 City Emida

(Give at least name of road + Distance to Road or Landmark)

Lt. Blk Sub. Name Parcel #
 RP-00070000 250

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK	AMOUNT	METHOD
Material	From To	Sacks or Pounds
Bentonite	1 1/2	400 LB
		Trimmed

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____
 Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	1 1/2	250	Steel	☒	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations Method Drill
 Screens Screen Type _____

From To	Slot Size	Number	Diameter	Material	Casing	Liner
270 270	3/8	80	4"	PVC	☐	☒
10 270	3/8	80	4"	PK	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

60 ft. below ground Artesian pressure _____ lb.
 Depth flow encountered _____ ft. Describe access port or control devices: _____

44 N 1 W 18

FORWARD WHITE COPY TO WATER RESOURCES

11. WELL TESTS:

☐ Pump ☐ Bailor

☒ Air☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
Est 20+ By Air Lift			

Water Temp. cold

Bottom hole temp. cold

Water Quality test or comments: Clear

Depth first Water Encounter _____

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	1	Top Soil		X
8	1	19	Decomposed Basalt		X
6	19	160	Decomposed Basalt		X
6	160	230	Hard Basalt		X
6	230	250	Decomposed Basalt	X	
6	250	270	Hard Basalt		X

Completed

Depth

270' Feet

(Measurable)

Date: Started

9/28/98

Completed

9/29/98

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Precision Drilling Firm No. 558

Firm Official

Date

9/29/98

and

Driller or Operator

Date

9/29/98

(Sign once if Firm Official & Operator)