

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	:	Long:	:

1. WELL TAG NO. D 0054681
DRILLING PERMIT NO. 852415
Water Right or Injection Well No. _____

2. OWNER:

Name Richard Jeness
Address PO Box 176
City Fernwood State ID Zip 83830

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 44 North ☒ or South ☐
Rge. 1 East ☐ or West ☒
Sec. 17 1/4 SE 1/4 SE 1/4
Gov't Lot _____
County Bennett
Lat: 47 : 9 : 34 N Long: 116 : 28 : 89 W
Address of Well Site 20443 Hwy 3, right at Santa
City Santa
Lt. _____ Blk. _____ Sub. Name _____
(Give at least name of road - Distance to Road or Landmark)

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
Bentonite	0	20	145X	Pour Around Pipe

Was drive shoe used? ☒ N Shoe Depth(s) 198
Was drive shoe seal tested? ☒ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	198	2.50	Steel	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____
Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method Air Perforator
Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
100	180	1/4x4	400	6"	Steel	☒	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method
None				

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

38 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 80 ft. Describe access port or control devices: Well Cap

12. WELL TESTS:

☐ Pump ☐ Bailor ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
12 GPM	Air Lift	AT 198 ft	2 hrs

Water Temp. 49° Bottom hole temp. _____
Water Quality test or comments: Cold & Clear NO Odor

13. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	3	TOP Soil		
8	3	198	Soft Broken Shale	☒	
			2 GPM AT 198 ft		
			10 GPM AT 120 ft		

RECEIVED

AUG 11 2008

NDWR/North

Completed Depth 198 (Measurable)
Date: Started 7-23-08 Completed 8-4-08

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Interstate Drilling LLC Firm No. 689

Principal Driller Ryan Suckale Date 8-6-08

and Driller or Operator II Debbie Mott Date 8/6/08

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.

44N 01W 17

FORWARD WHITE COPY TO WATER RESOURCES