

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

1. WELL TAG NO. D D0022811
 DRILLING PERMIT NO. 18-7070
 Other IDWR No. _____

2. OWNER: Roland Dack
 Name _____
 Address 1955 Round Lake Drive
 City St. Maries State ID Zip 83861

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N
 W

		X

 E
 S
 Twp. 47 North ☒ or South ☐
 Rge. 3 East ☐ or West ☒
 Sec. 34 1/4 SE 1/4 NE 1/4
 Gov't Lot _____ County Beneva
 Lat: _____ Long: _____
 Address of Well Site 1955 Rd. Lake
 City St. Maries
 (Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. _____ Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☐ New Well ☒ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT		METHOD
Material	From	To	Sacks or Pounds		

Was drive shoe used? ☐ Y ☐ N Shoe Depth(s) _____
 Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	-63'	250	Steel	☒	☐	☒	☐
4"	-5	-190	160	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations Method Drill
 Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
-130	-170	1"	20	1"	PVC	☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

36' ft. below ground Artesian pressure _____ lb.
 Depth flow encountered 152 ft. Describe access port or control devices: Well Cap

47N 3W 34

POSTED

11. WELL TESTS:

☐ Pump ☐ Bailor

Yield gal./min.	Drawdown	Pumping Level	Time
<u>5 gpm from 190</u>			

Water Temp. 50° Bottom hole temp. _____

Water Quality test or comments: Cloudy no odor

152 Depth first Water Encounter 150

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
6"	45	53	Basalt - Brown		
	53	62	Clay - Tan		
	62	64	Clay - Tan w/ Basalt		
	64	70	Clay - Tan		
	70	109	Clay - Tan w/ Basalt		
	109	113	Basalt - fractured		
	113	152	Clay - Tan w/ Basalt		
	152	156	Basalt - Broken w/ water		
	156	190	Basalt - Broken w/ clay		
			5 gpm		
			Deeper Hole		
			Added 24' 6" CSng		
			Hole was caving Below CSng.		

RECEIVED

FEB 11 2003

IDWR North

RECEIVED

IDWR North

Completed Depth 190 (Measurable)
 Date: Started 9-25-02 Completed 10-2-02

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name All-Ways Drilling Firm No. 510

Firm Official Stanley Wolfe Date 11-1-02

and Driller or Operator Alvin Carr Date 11-1-02

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES