Form 238-7
3/95
POSTED
Partnerships Consulting and Management Services

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT 096669


Use Typewriter or Ballpoint Pen

Office Use Only
Inspected by_____
Twp____Rge____Sec____
____1/4____1/4____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. TAG#D0003105
Other IDWR No. 91-97-D11 state

2. OWNER **Well Number:** 596
Name TOMLINSON, BOB
Address 1400 NW CENTER CT
City CDA State ID Zip 83814

3. LOCATION OF WELL by legal description
sketch map location must agree with written location



Twp. 45 ☑ North or ☐ South
Rge. 03 ☑ East or ☐ West
Sec. 14 1/4 NW 1/4 NE 1/4
Gov't Lot_____ County SHOSHONE
Lat: : : Long: : :
Address of Well Site ST. JOE PARCEL 1
City _____
(Give at least name of road + Distance to Road or Landmark)
_____ Blk. _____ Sub. Name _____

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☑ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
BENTONITE	0	18	8 BAGS	TEMP CASING

Was drive shoe used? ☐ Y ☐ N Shoe Depth(s) 0
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	74	.250	STEEL	☑	☐	☑	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☐ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
22 ft. below ground Artesian pressure_____ lb.
Depth flow encountered_____ ft. Describe access port or control devices: _____

NWNE 14 45N 3E

11. WELL TESTS:
☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
40+			

Water Temp. _____ Bottom Hole Temp _____
Water Quality test or comments: _____
_____ Depth first Water encountered _____

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Water Y	Water N
8	0	3	Topsoil Small Boulders	☐	☑
8	3	18	Sand & Gravel Small Boulder	☐	☑
6	18	32	Sand Gravel Small Boulders	☐	☑
6	32	63	Sand & Gravel Clay Seems Tan	☑	☐
6	63	73	Sand & Gravel Coarse	☑	☐
6	73	78	Shale Fractured Soft	☑	☐

RECEIVED
SEP 08 1997
NORTHERN REGION
IDWR

Completed Depth 78' (Measurable)
Date: Started 8/18/97 Completed 8/18/97

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H20 WellService, Inc. Firm No. 448
Firm Official _____ Date 8/18/97
and
Supervisor or Operator _____ Date 8/18/97
(Sign Once if Firm Official and Operator)
(Louie Hanner)