

91-7683 GODSBY PIN 46N02W2NWSWT WELL D005650



Unit 11

1-4 99 77495

Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Office Use Only			
Inspected by _____			
Twp _____	Rge _____	Sec _____	
_____ 1/4	_____ 1/4	_____ 1/4	
Lat: _____	: _____	Long: _____	: _____

1. WELL TAG NO. D 0005484-5650
 DRILLING PERMIT NO. 91-98-N-12 NOV 02 1998
 Other IDWR No. _____

11. WELL TESTS:

☐ Pump ☐ Bailer

☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
15 G.P.M.			

 Water Temp. Cold Bottom hole temp. Cold

 POSTED Quality test or comments: good

 Depth first Water Encounter 255

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	3	Top Soil		X
8	3	15	Broken Shale		X
8	15	19	Hard shale		X
6	19	255	Hard shale		X
6	255	265	Broken Shale	X	
6	265	305	Hard Shale		X
6	305	325	Broken Shale	X	

 Completed Depth 325 Feet (Measurable)
 Date Started 10/19/98 Completed 10/21/98

13. DRILLER'S CERTIFICATION

We certify that all minimum well construction standards were complied with at the time the rig was removed.

 Company Name Precision Drilling Firm No. 558

 Firm Official Jamuel Caman Date 10/21/98

 and Driller or Operator Jamuel Caman Date 10/21/98

(Sign once if Firm Official & Operator)

Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

1. WELL TAG NO. D 0005484-5650
 DRILLING PERMIT NO. 91-98-N-12 NOV 02 1998
 Other IDWR No. _____

11. WELL TESTS:

☐ Pump ☐ Bailer

☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
15 G.P.M.			

 Water Temp. Cold Bottom hole temp. Cold

 POSTED Quality test or comments: good

 Depth first Water Encounter 255

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	3	Top Soil		X
8	3	15	Broken Shale		X
8	15	19	Hard shale		X
6	19	255	Hard shale		X
6	255	265	Broken Shale	X	
6	265	305	Hard Shale		X
6	305	325	Broken Shale	X	

 Completed Depth 325 Feet (Measurable)
 Date Started 10/19/98 Completed 10/21/98

13. DRILLER'S CERTIFICATION

We certify that all minimum well construction standards were complied with at the time the rig was removed.

 Company Name Precision Drilling Firm No. 558

 Firm Official Jamuel Caman Date 10/21/98

 and Driller or Operator Jamuel Caman Date 10/21/98

(Sign once if Firm Official & Operator)

2. OWNER: DOWN North
 Name Monty J. Gadsby
 Address HCO 2 Box 198-D
 City St. Maries State Id Zip 83861

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

Section 2

Twp. <u>46</u>	North ☒ or South ☐
Rge. <u>02</u>	East ☐ or West ☒
Sec. <u>24</u>	SE 1/4 SE 1/4 1/4
Gov't Lot <u>24</u>	County <u>Benedict</u> 100 acres
Lat: _____	Long: _____
Address of Well Site <u>Hell's Gutten-</u>	
City <u>St. Maries</u>	

Parcel # RP-00630000230-A

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK	AMOUNT	METHOD
Material	From To Sacks or Pounds	
<u>Bentonite</u>	<u>0</u> <u>19</u> <u>200 lbs.</u>	<u>packed</u>

 Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 19 ft.

 Was drive shoe seal tested? ☒ Y ☐ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6"</u>	<u>+1</u>	<u>19</u>	<u>280</u>	<u>Steel</u>	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations

Method

Screens

Screen Type

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

70 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

46 N 2 W 2

FORWARD WHITE COPY TO WATER RESOURCES