RECEIVED
OCT 21 1996
NORTHERN REGION
IDWR

Form 238-7
3-95

POSTED

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

096894

Office Use Only
Inspected by _____
Twp____ Rge____ Sec____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 94-96N-34
Other IDWR No. _____

2. OWNER:
Name Mark & Pat LANGHANS
Address 15708 Tiger MTN. Rd SE
City Issaquah State WA Zip 98027

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 47 North ☒ or South ☐
Rge. 2 East ☐ or West ☒
Sec. 3 , ____ 1/4 NONE 1/4 NONE 1/4
(10 acres / 40 acres / 160 acres)
Gov't Lot ____ County _____
Lat: : : Long: : :
Address of Well Site ½ m. up EVANS Ck. Rd - By Big BARN 90 R to Y
(Give at least name of road or Distance to Road or Landmark)
City MEDIMONT
LOT 4 & SEABENS (ACROSS THE CREEK)
Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	1	20	500 LBS	Trimmie

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 85
Was drive shoe seal tested? ☒ Y ☐ N How? Pound

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1	95	250	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☐ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
50 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: _____

3 47N 2W

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
100+	By Air	Lift	

Water Temp. cold Bottom hole temp. cold
Water Quality test or comments: Clean
Depth first Water Encountered 185'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	1	3	Top Soil		✓
8	3	15	Light Brown Clay		✓
8	15	75	Brown Clay		✓
8	75	85	Broken Shale		✓
6	85	185	Hard gray Shale		✓
6	185	190	Fractured Shale	✓	
6	190	225	Hard Shale		✓
6	225	330	Fractured Shale	✓	
6	330	345	Hard Shale		✓
6	345	350	Cracked Shale	✓	

Completed Depth 350 (Measurable)
Date: Started 10-12-96 Completed 10-13-96

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Precision Drilling Firm No. 558
Firm Official [signature] Date 10-13-96
and
Supervisor or Operator [signature] Date 10-13-96
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES