

28 2013
IDWR / NORTH
E)

94-8315 GUY POU PIN RP50N02E340460 (2009 IMAGE)



SCANNED

FEB 28 2013

Amended Claim
IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

RECEIVED
FEB 28 2013
IDWR/NORTH

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 1/4 1/4
Lat : : Long: : :

1. WELL TAG NO. **D0054778**

DRILLING PERMIT N _____

Other IDWR No _____

2. OWNER:

Name **Dan Guy**

Address **silverlined Homes/ Eli Goodner / P O Box 757**

City **Kellogge**

State **ID**

Zip **83837**

3. LOCATION OF WELL by legal description:

N
W E S

		X	

Twp **50N** North ☒ or South ☐
Rge **02E** East ☐ or West ☒
Sec **34** 1/4 NW 1/4 NE 1/4
10 Ac 40 Ac 160 Ac
Gov't Lot _____ County **Shoshone**
Lat _____ Long _____
Address of Well Site: (see next line)

oda river rd to river edge lane

City **kinson**

Lot _____ Blk _____ Sub. Name (see next line) _____

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			Amount	Method
Material	From	To	Sacks/Lbs	
BENTONITE	0	38	12 SACKS	DRY POOR

Drive Shoe Used? ☒ Y ☐ N Shoe Depth(s) **38**

Drive Shoe Seal Tested? ☐ Y ☒ N How? _____

8. CASING/LINER

Diam	From	To	Gauge	Material	Casng	Liner	Weld	Thrded
6	+2	38	0.250	STEEL	☒	☐	☒	☐
4	-10	440	0.200	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length Headpipe **N/A** Length Tailpipe **N/A**

9. PERFORATIONS/SCREENS

- ☒ Perforations? Method **DRILL**
☐ Screens? Screen Type _____

From	To	Slot	Nmbr	Diam	Material	Casng	Liner
400	440	3/8	500	3/8	PVC	☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL or ARTESIAN PRESSURE

140 ft. below ground. Artesian pressure **0** lb.
Depth flow encountered **210** ft. Describe access port or control devices: **CAP WELDED**

11. WELL TESTS:

- ☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pump Level	Time
3GPM EST	100%	440	2HRES

Water Temp. **COLD** Bottom hole temp. **COLD**

Water Quality test or comments: (below) Depth first Water Encountered **210**

CLEAR

12. LITHOLOGIC LOG (Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality and Temperature	Water
8	0	27	CLAY CEMENTED GRAVEL	☐ ☒
8	27	38	DECOMPOSED GRANIT	☐ ☒
6	38	69	DEC GRANIT	☐ ☒
6	69	210	HARD DEC GRANIT	☐ ☒
6	210	228	WHITE QUARTZ 2.GPM 210	☒ ☐
6	228	440	HARD BLACK AND WHITE GRANIT	☒ ☐
			1 GPM 410	☐ ☐

RECEIVED

SEP 23 2001

IDWR/North

Completed Dept **440** (Measurable)
Date: Started **7/16/2008** Completed **7/21/2008**

13. DRILLERS CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm **United Drilling Inc.** Firm No **414**

Firm Official **Timothy R. Volking** Date **7/21/2008**

Supervisor or Operator **Timothy R. Volking** Date **7/21/2008**