

RECEIVED

DEC 05 2014

IDWR / NORTH

Identify

Identify from: Taxlots

Taxlots

NORLANDER, QUINTON

Location: 2,303,972.103 1,857,795.759 Meters

Field	Value
ID	4168621
UPDATED	5/19/2014
PIN	53N02W318750
OWNER	NORLANDER, QUINTON
ADDRESS1	12080 E TROUT POND RD
ADDRESS2	
CITY	ATHOL
STATE	ID
ZIPCODE	83801
P_ADDRESS	12080 E TROUT POND RD
P_ZIPCODE	
SUB_NAME	
LEGAL1	TX#15386, TX#19217 EX TX#19216 [IN S2-SE]
LEGAL2	534- IMP RES RURAL TRACT
LEGAL3	
LEGAL4	
LEGAL5	
LEGAL6	<null>
ACRES	11.3
COUNTY	Kootenai
SOURCE	
YEAR_BUILT	1999

Identified 1 feature

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

REVISED WELL REPORT

SEP 29 1999

076998

Office Use Only			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat	:	:	Long
:	:	:	:

1. WELL TAG NO. D10366

Drilling Permit No:

Other IDWR No.

96-99-N-173

IDWR/North

2. OWNER

Well Number:

Name Norlander, Quint

909

Address 24355 N Goodhope

City Athol

State Id

Zip 83801

3. LOCATION OF WELL by legal description

sketch map location must agree with written location

		X

Twp. 53



North or



South

Rge. 03



East or



West

Sec. 34



1/4 SE



1/4 NE



1/4

Gov't Lot

County

KOOTENAI

Lat:

:

Long:

:

:

Address of Well Site off Goodhope Rd.

City Athol

(Give at least name of road + Distance to Road or Landmark)

Lt. Blk.

Sub. Name

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply (Replacement, etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
BENTONITE	0	25	4 Bags	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 38Was drive shoe seal tested? ☐ Y ☐ N How?

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	38	.250	Steel	☒	☐	☒	☐
4	-9	74	.160	PVC	☐	☒	☐	☐

Length of Headpipe

Length of Tailpipe

9. PERFORATIONS/SCREENS

☐ Perforations Method☒ Screens Screen Type PVC

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
64	84	10		4	PVC	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

-2 ft. below ground Artesian pressure lb.

Depth flow encountered ft. Describe access port or control devices:

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
10-12 GPM		84	1 HR

Water Temp.

Bottom Hole Temp

Water Quality test or comments:

Depth first Water encountered 48'

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Water	
				Y	N
8	0	30	Clayish Topsoil Tan	☐	☒
8	30	48	Granite Decomposed Gray W/Water 5	☒	☐
8	48	70	Granite Salt & Pepper W/Green	☐	☒
8	70	84	Granite Salt & Pepper W/Green & Ros	☒	☐
			Set 20' of 10 Slot Screen at bottom of Well.		
RECEIVED DEC 05 2014 IDWR / NORTH					
Completed Depth 84' (Measurable)					
Date: Started 7/30/99 Completed 7/30/99					

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O Well Service, Inc. Firm No. 448

Firm Official John W. Hanner Date 7/30/99

and

Supervisor or Operator Date 7/30/99

(Sign Once if Firm Official and Operator)

(Louie Hanner)

53N 3W 34